

RAINFALL AT *Malvern Hills Upper Wyck*

Lat. _____

Lon. _____

County of *Hereford*

Rain Gauge, by _____

Observer *Baldwin Latham Esq C.E.*

Severn - 7.

Diameter						5					
Height						10					
Altitude						1006					
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January						3.95	.52	2.05	.44	3.40	
February						.12	.31	2.62	1.10	2.60	
March						1.81	2.36	2.87	.53	.60	
April						2.24	.71	1.72	1.69	1.97	
May						.93	.23	.88	4.02	2.53	
June						1.23	1.92	2.54	.91	1.30	
July						2.52	1.68	1.08	1.25	.97	
August						2.11	1.67	4.26	2.54	1.04	
September....						.63	4.81	2.30	.63	3.15	
October.....						2.86	2.07	1.58	3.19	2.41	
November....						4.10	.68	1.73	2.07	1.63	
December						1.43	3.17	2.71	2.18	2.95	
TOTALS						23.93	20.13	26.34	20.55	24.55	

RAINFALL AT *Malvern Hills Upper Wyck*

Lat. Lon. County of *Hereford*

Rain Gauge, by Observer *Baldwin Lathom Esq C.E.*

Section - 2.

Diameter ..	5										
Height	10										
Altitude ..	1006 ft										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	3.92	1.57	.58	2.28	2.02	.83					
February ..	5.17	1.09	1.39	1.46	3.52	.61					
March	1.03	1.44	1.35	2.71	.84	3.30					
April	1.41	1.30	2.20	1.62	.92	2.89					
May	2.18	.83	1.95	4.69	1.68	.39					
June	3.19	3.25	3.26	4.24	.48	3.46					
July	1.43	2.91	1.34	2.49	2.02	.37					
August	3.59	3.06	4.04	3.58	1.91	6.16					
September..	.54	1.51	2.61	2.66	2.42	1.24					
October....	2.15	1.45	1.82	5.46	.42	1.28					
November..	2.35	.90	2.99	1.11	.67	2.74					
December ..	5.30	3.36	1.42	1.40	1.76	53					
TOTALS ..	32.26	22.67	24.95	33.70	18.61	23.80	N.R.				

3

1904 Not published in B.R. too small

1905