

RAINFALL AT *Ogbourne Marley*

Lat.

Lon.

County of *Wilt*

Rain Gauge, by

Observer

Rev T. A. Preston

Kennet - 5.

R. P. Farmer Esq

Diameter			5								
Height			1.1								
Altitude											
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.
January			1.73	3.68	3.80	2.84	3.72	2.83	.64	1.05	
February			2.41	5.22	2.43	4.22	.64	.88	1.14	2.65	
March			1.94	1.37	2.69	1.39	2.16	2.29	4.09	3.05	
April			5.33	.89	1.56	2.49	2.63	1.15	1.71	2.79	
May			3.08	1.97	1.38	2.62	3.75	1.75	1.42	2.01	
June			6.02	2.14	3.31	1.61	.69	1.51	2.24	1.41	
July			3.77	2.99	3.21	.44	2.60	1.19	4.68	3.39	
August		5.80	2.48	1.05	1.30	.87	1.29	2.55	1.78	2.94	
September		1.69	3.41	3.92	1.62	4.47	2.24	2.25	1.13	1.22	
October		1.35	6.73	2.82	1.03	4.65	4.76	2.21	1.17	2.40	
November		4.24	4.71	4.07	1.82	4.77	3.59	3.06	5.17	1.19	
December		3.52	4.36	1.01	2.83	1.33	5.72	2.15	2.52	1.94	
TOTALS			45.97	31.08	26.98	31.70	33.79	23.85	27.69	26.04	

RAINFALL AT

Ogbourne Maizy

Lat. _____

Lon. _____

County of

Wilts

Rain Gauge, by _____

Observer

H. P. Dixon Esq

Kennet - 5.

Diameter . . .	5										
Height	1 0										
Altitude	...										
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	3.56	3.16	.93	2.31	2.93	3.26					
February	78	.00	1.36	4.69	2.35	.27					
March	1.37	2.09	.73	.33	2.45	2.45					
April	1.66	1.30	.70	.06	1.80	2.52					
May	1.29	2.56	1.00	1.31	1.87	.19					
June	2.54	.84	1.51	1.09	2.60						
July	3.94	2.74	2.66	3.99	4.46						
August	1.86	5.85	3.55	1.54	2.27						
September . . .	1.37	1.57	2.20	1.62	2.24						
October	1.04	6.91	4.95	4.30	3.74						
November	2.07	3.09	2.17	2.56							
December	1.10	5.61	1.15	3.09	3.42						
TOTALS . . .	22.58	35.72	22.91	26.89							