

RAINFALL AT Rhayader (Gryddellau)

Lat. _____

Lon. _____

County of Radnor

Rain Gauge, by _____

Observer Mr. N. Lewis

Wye - 1.

J. M. Youde Esq. C.E.

Diameter		5									
Height		1 0									
Altitude		1710									
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January			7.50	3.65	8.20	5.10	4.90	3.15	4.20	10.50	
February			4.00	9.35	9.35	.25	3.65	6.35	4.30	6.40	
March			1.00	1.35	5.55	7.30	9.55	6.85	3.30	2.70	
April			1.85	.40	3.45	3.45	2.60	5.55	4.23	7.70	
May			3.30	4.10	5.10	1.00	.25	1.83	5.10	5.40	
June			2.90	5.30	3.40	1.15	3.05	1.17	5.00	1.80	
July			5.00	4.70	8.15	7.75	4.30	4.20	2.02	4.50	
August			5.30	5.30	7.50	6.15	5.50	6.65	6.35	2.20	
September . . .			6.95	6.40	2.65	2.05	9.30	7.95	2.48	6.50	
October	#	12.00	8.00	6.70	8.70	7.50	7.25	4.15	5.52	4.90	
November		7.00	5.30	6.50	7.75	8.55	2.00	5.75	5.15	5.25	
December		14.00	5.80	7.85	7.65	7.00	9.85	9.53	8.60	4.50	
TOTALS			56.90	61.60	77.45	57.25	62.20	63.13	56.25	62.35	

RAINFALL AT

27

Rhayader, Pysgellau

Lat.

Lon.

County of

Radnor

Rain Gauge, by

Observer

G. M. Youndie Esq. Cl.
E. Anthony Esq.

Wye - 1.

M

Diameter ..	5											
Height	10											
Altitude ..	1710											
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.	
January ..	7.50	6.70	4.60	8.40	6.30	5.50	10.50	4.60				
February ..	4.60	1.60	1.90	4.40	5.70	4.20	6.50	2.70				
March	1.00	4.40	4.00	9.90	2.70	7.40	5.40	4.10				
April	4.20	5.30	2.70	3.50	4.80	5.90	1.80	4.60				
May	3.80	1.20	4.50	4.60	2.80	1.30	4.60	4.70				
June	4.80	4.60	4.00	3.50	1.70	2.30	4.10	7.30				
July	2.20	2.90	4.10	4.50	2.80	2.70	4.40	6.50				
August	7.50	5.70	5.30	8.20	4.80	8.20	5.60	5.80				
September ..	2.70	4.10	4.30	7.50	2.20	2.70	2.20	1.00				
October	8.20	5.80	5.20	13.80	3.80	4.70	8.40	8.30				
November ..	7.10	5.30	4.90	8.30	5.30	4.40	6.70	4.70				
December ..	8.60	8.30	6.70	5.80	5.40	2.10	7.70	7.30				
TOTALS ..	62.20	55.90	52.20	82.40	48.30	51.40	67.90	61.60				

in up in up in

1900 Sep 28 New gauge fixed in place of old
1904 Rhayader Station