

RAINFALL at

Swindale Head

County of WestmorlandObserver F. H. Hill & Sons C.River Basin Iden. r.Snowdon Rain Gauge, by
Copper no bottle

Diameter ...										5		
Height										1.0		
Altitude ...										1029		
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.	
January ...										728		
February ...										1.40		
March										5.88		
April										3.11		
May										1.90		
June										2.90		
July										1.55		
August										4.55		
September...										5.20		
October ...									12.79	2.34		
November..									5.10	5.51		
December...									8.48	10.65		
TOTALS ...										52.17		

Reported ponding : 25" too low.

+ C.S. 14 mi. S. 29 in clear open meadow on N. of valley about 150 ft above stream, lands slopes to S + W, poor site. Recommended check S. at bottom of valley in flat meadows, with trees on S.W.

H. Lewis said (XII.21) all recommendations have been carried out.

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.

RAINFALL at Swindale HeadCounty of WestmorlandObserver Messrs F. H. Hill & Sons G.E.River Basin Edens 1L. Holme Lewis CE (1921)Swindale Rain Gauge, by
Copper no bottleManchester Corp. W.W.

Diameter ...	5										
Height	1	0									
Altitude ...	1029										
Year	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930 MEANS.
January ...	8.64	11.82	5.90	5.71	4.24	9.72	11.22	7.76	16.54	2.11	11.47
February ...	7.27	20	7.19	11.01	66	11.21	7.94	44.1	6.79	1.52	6.0
March	8.28	12.25	5.53	3.58	1.39	2.12	2.98	6.91	8.24	.96	5.00
April	7.43	1.49	4.41	5.03	3.24	7.70	4.29	3.74	1.95	2.85	2.87
May	7.83	4.39	3.74	4.36	7.79	9.18	3.27	3.12	1.35	5.88	2.70
June	1.97	18	3.08	1.62	4.02	.15	6.21	4.33	9.26	2.15	4.87
July	9.13	4.47	8.48	4.13	7.47	1.77	4.92	5.82	5.02	7.87	4.81
August	4.59	9.11	5.25	12.67	5.45	6.05	6.59	8.25	9.79	7.03	9.68
September...	2.97	2.56	5.24	6.93	11.06	6.94	5.55	8.40	4.28	2.37	5.41
October	2.43	2.73	2.81	14.80	7.66	8.52	5.26	8.84	13.94	8.34	13.41
November...	6.45	3.09	4.21	6.99	4.94	2.04	12.63	5.65	14.91	12.78	8.79
December...	6.36	11.69	12.72	6.86	14.79	6.95	1.15	1.64	6.14	12.68	7.41
TOTALS...	73.35	63.98	68.56	83.39	75.60	72.35	72.01	68.87	98.21	65.44	76.72

1920 Gauge inspected G.E. 14.11.20. See last sheet

Rejected from survey : 25" too low.

Position of Station on reduced Ordnance Survey
Map, 2 miles to 1 inch Series

No. of Map

Reference No.

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge	Direction from gauge

RAINFALL at Swindale Head,County of Westmorland, Observer Manchester Corpn. W.W.River Basin Eden - 1

Type of Gauge

Annual Average in. based on years obs. un-weighted. Period of average Ref.

660604/26.

Diameter	5.											
Height	1.0.											
Altitude	1025.											
Year	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	Means	
January	5.57											
February	5.57											
March	1.53											
April	3.39											
May	4.57											
June	6.88											
July	6.36											
August	5.32											
September	3.16											
October	5.06											
November	15.52											
December	5.40											
TOTALS	68.33											

Site abandoned 2/12/31, the g. being fixed alongside the recording g. on selected site of Burn Banks gauge. see Encl. d. 23.5.32.

Position of Station on reduced Ordnance Survey Map, } No. of Map..... Reference No.....
1 mile to 1 inch Series

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge	Direction from gauge