

RAINFALL AT Portland Easton

Lat. _____

Lon. _____

County of Dorsetshire

Synthes Rain Gauge, by _____

Observer R.S. Henshaw Esq C.E.

Form - 3.

Diameter ...										5	
Height										1.6	
Altitude ...										265*	
Year ...	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ...										.87	
February ...										.21	
March										4.00	
April										1.26	
May										1.59	
June										3.36	
July										1.87	
August										2.73	
September ..										2.84	
October ...										6.32	
November ..										.87	
December ...										4.83	
TOTALS ...										30.75	

1909 Portland Church 5 ferge's
 Easton Station 1/4 mile N.W.
 "all objects well away"

RAINFALL at Portland EastonCounty of DorsetshireObserver R. L. Henshaw Esq. C.E.River Basin Frome + C 3Sunderland Rain Gauge, by

Diameter ...	5										
Height	16										
Altitude ...	265 ft										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	3.22	1.16	5.06	5.11	.98						
February ...	4.01	1.55	2.59	1.73	5.12						
March	.76	2.69	4.66	2.59	5.39						
April	1.35	1.56	.00	2.45	1.21						
May	1.94	.94	2.14	1.92	1.50						
June	2.09	1.79	3.53	.41	.39						
July	3.56	.11	2.04	.45	4.31						
August	2.03	.74	5.14	1.46	3.57						
September ..	.17	.78	2.33	3.04	1.69						
October ...	4.85	4.46	4.88	3.52	2.21						
November ..	4.54	4.08	1.84	2.94	5.08						
December ...	5.27	7.60	4.94	2.26	6.76						
TOTALS ...	32.79	27.46	39.15	27.88	38.11						

1910 "all objects well away"

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
1910	50° 32' 35" N	2° 25' 55" W	Easton	1/4 mile	NW	St George	1/2 mile	NW