

RAINFALL AT *Sheffield* *Gleadless Handsworth W.W.*

Lat.

Lon.

County of *York W.R. Southern*

Rain Gauge, by *N43*

Observer *J. R. Robinson Esq.*

Use. Don Y.

Diameter ..		8									
Height		0 5 0 8						1 0			
Altitude ..		700									
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..			1.75	3.14	3.46	1.49	4.33	1.23	1.86	1.65	
February ..			2.35	2.03	5.82	1.39	3.25	3.00	2.34	.87	
March			1.79	3.31	2.41	3.67	2.01	2.20	3.42	5.14	
April			2.96	2.08	2.41	2.94	.47	2.23	2.55	1.62	
May			3.49	4.33	3.03	.64	2.29	4.51	2.74	2.04	
June			1.81	2.04	.62	3.91	2.46	4.35	1.89	3.38	
July			2.29	2.49	2.98	2.16	1.73	2.29	2.50	3.87	
August			5.11	5.36	4.04	4.58	2.32	2.46	3.24	2.90	
September ..			1.88	4.27	1.50	1.50	1.17	.65	1.93	2.72	
October			3.45	6.76	1.03	2.11	6.79	6.17	1.52	3.16	
November ..		4.16	2.64	1.87	2.20	4.58	4.12	3.14	1.56	.79	
December ..		4.23	2.58	1.98	2.26	.99	2.95	2.55	2.41	6.14	
TOTALS ..			32.10	39.66	31.26	29.96	33.89	34.78	27.96	34.28	

1901 Gleadless Church 1 mile SSE

Sheffield " 2 " NNW

Gauge much exposed to heavy winds from the north west of Sheffield

1903 Sheffield Station Mill by 2 miles NW

Trees 12 ft high 30 yards W.S.W

1907 1/2 in gauge raised 4 in

+ Inspected

RAINFALL at Sheffield W.D. HeadlessCounty of W.R. YorkshireObserver Mr R. RobinsonRiver Basin Ouse - Don 7Rain Gauge, by N+3

Diameter ...	8										
Height	1 0										
Altitude ...	700 T										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	2.39										
February ...	4.00										
March	.80										
April	2.35										
May	2.84										
June	3.60										
July	2.22										
August	4.38										
September ..	.44										
October ...											
November ..											
December ...											
TOTALS ...											

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.