

RAINFALL AT *Garden Mill, Beltingham, Co. Antrim*

Lat. Lon. County of *Northumberland*

Rain Gauge, by Observer *H. C. Newbery*

S. Tyne - 2.

Diameter ..			5								
Height			1 0				3. 0				
Altitude ..			3 20								
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..			2.16	4.28	2.54	.88	3.64	.93	2.17	2.39	
February ..			1.12	4.98	2.21	1.22	1.30	1.46	3.83	2.87	
March			2.04	3.65	2.24	2.48	2.03	2.73	3.64	4.11	
April			1.44	1.84	2.88	4.15	1.19	2.29	2.10	2.22	
May			2.19	2.62	2.56	.75	4.75	3.91	2.34	1.06	
June			1.75	1.66	1.12	1.34	1.93	2.92	.87	3.02	
July			2.64	4.99	1.54	1.19	1.87	2.28	2.48	3.53	
August			2.10	3.66	3.17	3.91	4.71	2.79	2.58	2.72	
September ..			1.03	3.33	.63	2.30	1.10	.41	3.26	2.33	
October			2.26	3.37	9.23	.67	2.47	4.87	6.52	2.75	3.58
November ..			5.87	1.24	2.16	3.74	3.36	3.35	1.47	2.06	1.19
December ..			4.24	3.46	1.87	1.88	1.12	2.79	3.91	1.40	3.75
TOTALS ..			24.54	44.27	25.18	25.17	33.53	31.52	29.02	32.77	

m m m m s s

RAINFALL at Bardon Mill Beltingham VicarageCounty of Northumberland Observer Rev H.C. NewberyRiver Basin South Tyne 2

Rain Gauge, by _____

Diameter ...	5										
Height	3.0										
Altitude ...	323										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	4.37	2.02									
February ...	4.40	2.93									
March	.87	2.37									
April	2.54										
May	2.33										
June	1.61										
July	4.06										
August	4.16										
September ..	31										
October ...	2.84										
November ...	3.23										
December ...	2.11										
TOTALS ...	32.83										
	7										

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.