

RAINFALL AT Bromfield Prior Station

Lat. _____

Lon. _____

County of Shropshire

Rain Gauge, by _____

Observer Rev. W. Selwyn

Season 3.

in m/s Bed does

Diameter		5									
Height		1									
Altitude		300									
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January			2.18	2.13	3.01	4.24	.75	1.91	.32	4.89	
February			1.57	3.57	2.34	.16	.44	2.14	1.64	4.43	
March			.84	.86	1.75	2.20	2.98	3.39	.63	1.09	
April			.77	.36	2.07	2.62	1.04	2.33	1.81	2.34	
May			2.72	3.30	3.70	.98	.21	1.08	3.63	2.28	
June			2.88	1.58	2.41	2.06	2.14	2.14	1.50	2.52	
July			2.06	3.02	3.94	2.29	1.43	1.09	1.18	1.17	
August			3.05	1.95	2.70	3.12	1.69	3.48	1.76	.42	
September....			2.22	1.71	2.42	.89	5.18	1.96	1.30	1.91	
October			2.34	2.55	4.50	2.90	3.32	1.71	4.60	3.05	
November....		2.76	2.62	1.40	4.23	6.01	.88	1.84	2.10	3.09	
December		4.68	1.36	4.70	2.08	2.69	4.36	4.92	2.89	2.65	
TOTALS			24.61	27.13	35.15	30.16	24.42	27.99	23.36	29.84	

1894 Bromfield Ch 14 miles ^{N.W.} W

RAINFALL AT *Bronfield Priors Halton*

Lat. Lon. County of *Salop*

Rain Gauge, by Observer *Miss Reddies* *Miss Keadie*

Seven - 3.

Diameter ..	5											
Height	1 0			3 0								
Altitude ..	300											
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.	
January ..	3.91	2.16	1.38	3.46								
February ..	4.39	1.20	1.30	2.86								
March	.91	3.26	1.65	4.63								
April	1.29	2.57	2.32	1.92								
May	2.52	.86	2.37	4.04								
June	3.00	2.06	3.29	2.99								
July	2.43	2.58	2.17	2.45								
August	4.29	1.54	5.81	5.26								
September ..	.96	2.07	1.50	3.81								
October	3.86	1.86	2.94	7.89								
November ..	2.98	1.27	3.22	1.84								
December ..	5.57	5.20	2.36	2.54								
TOTALS ..	36.11	26.63	30.31	43.69								

1900 Bronfield Church 1/4 miles N.W.

1902 Jan 7 31st Gauge moved 100 yards gauge taken over
by Miss Reddies