

RAINFALL AT *Broughton in Furness*

Lat..... Lon..... County of *Lancashire*
 Rain Gauge, by..... Observer *Rev. F. A. Nicholson*

No 1331-1915 565

Diameter.....			5								
Height			1.3						1.3		
Altitude.....			10								
Year.....	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	MEANS.
January.....			<i>{2000}</i> 6.61	5.95	7.95	3.87	11.40	5.74	2.50		
February.....				1.43	4.34	2.03	6.18	5.04	4.00	4.27	
March.....			<i>7.82</i>	5.12	3.98	1.67	3.94	4.81	2.75	3.15	
April.....			2.10	.85	1.44	1.81	3.94	2.37	2.58	2.08	
May.....			3.37	2.51	.86	3.25	.51	3.97	4.15	2.42	
June.....			6.79	3.62	.92	4.83	4.76	3.73	3.65	3.58	
July.....			4.98	6.41	2.85	3.71	2.96	5.55	.73	8.76	
August.....			7.28	5.86	9.05	4.49	4.61	7.97	7.07	7.29	
September.....			10.30	3.50	5.78	7.78	5.67	3.07	5.95	5.77	
October.....			10.05	9.04	8.14	7.61	4.26	12.39	6.29	3.95	
November.....			5.38	3.98	9.24	7.41	3.67	10.93	2.78	1.36	
December.....			7.64	3.23	5.47	4.00	14.12	7.15	2.58	3.78	
TOTALS.....			<i>65.85</i>	52.16	58.02	56.54	58.49	78.38	48.27	48.91	

1878 A low tree 20ft distant

Jan Feb 1872 very roughly estimated

RAINFALL AT Broughton-in-Furness

80

Lat. _____

Lon. _____

County of _____

Lancashire

Rain Gauge, by _____

Observer _____

Rev. F.A. Mallison

Ruddon 26.1

Diameter	5										
Height	1.3										
Altitude	40 T										
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.
January	1.59	1.04	4.65	8.61	8.19		5.92	3.98	2.82	3.39	
February	5.17	6.44	5.44	6.14	5.09		2.31	3.35	1.75	3.73	
March	3.20	7.54	4.96		5.31		8.31	2.62	4.24	4.38	
April	2.74	2.18	5.93	8.55	1.44		3.12	2.49	2.19	2.97	
May	2.59	5.96	3.30	2.14	4.08		6.96	2.29	2.26	4.34	
June	3.61	6.09	6.36	4.33	.74		2.34	.58	1.86	1.75	
July	4.25	7.89	8.65	2.42	6.87		6.79	2.65	8.87	3.16	
August	1.84	5.79	6.70	6.59	1.39		(2.42)	1.49	4.95	7.18	
September	5.33	4.39	3.46	6.44	5.28		7.74	4.39	2.50	4.96	
October	1.52	3.68	5.44	6.60	6.07		6.34	5.49	5.54	7.18	
November	7.20	8.23	9.59	7.06	2.31		7.14	3.30	7.64	3.51	
December	7.17	5.98	4.96	5.98			7.36	4.80	5.37	8.12	
TOTALS	46.21	65.21	69.44				(66.75)	37.43	49.99	54.67	

(39.05)

1886 Broughton Church 1/4 mile S.W.

Trees 30ft high 21 to 24 ft E.W.

1886 Aug. Gauge blown over

1888 * Measuring jars found to be inaccurate

RAINFALL AT *Broughton in Furness Orchard Head*

Lat. _____

Lon. _____

County of *Lancashire*

Rain Gauge, by _____

Observer

Rev F.A. Mallison

C.P. Chambers Esq

Duddon - 61.

Diameter	5										
Height	13										
Altitude	40								100		
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	8.87	3.27	6.69	2.93	6.33	3.45	4.56	1.54	5.84	6.75	5.023
February	1.26	.82	2.20	10.12	8.41	1.24	4.41	3.51	5.43	3.30	4.070
March	6.19	2.51	2.04	3.38	2.94	6.21	7.37	7.64	2.04	3.52	4.414
April	2.54	3.37	2.40	1.56	1.41	3.47	2.55	3.73	4.94	5.42	3.129
May	3.82	2.75	6.59	2.86	3.94	.71	.63	2.94	3.91	4.80	3.295
June	6.38	1.99	3.32	1.58	5.01	1.59	4.20	7.58	3.56	1.93	3.714
July	5.29	3.42	3.25	5.54	5.23	6.66	5.66	2.56	1.14	3.82	4.257
August	6.90	10.38	10.41	7.99	6.61	5.61	4.78	7.09	9.82	1.42	7.101
September	6.61	7.19	8.40	7.65	.98	1.77	8.33	6.12	3.27	7.27	5.459
October	6.08	6.30	5.93	8.06	6.64	7.27	6.46	3.57	5.32	3.69	5.932
November	13.78	8.06	5.68	4.39	7.50	4.95	1.75	8.43	6.18	4.52	6.524
December	.96	11.00	4.63	6.62	6.77	7.07	8.49	8.09	6.86	5.73	6.622
TOTALS . . .	68.68	61.36	61.54	62.68	61.77	50.00	59.19	62.80	58.31	52.17	59.850

1898 Gauge moved to Orchard Head Feb 4th 1/8 mile SE
 Broughton Church 1 mile SE
 Shrub 5 ft high 10 ft W

RAINFALL AT *Broughton-in-Furness*

Lat.

Lon.

County of *Lancashire*

North

Snodden Rain Gauge, by

Observer *C. Chambers Esq*

Dutton 1

Diameter ..	5										
Height	1 0						1.3				
Altitude ..	101										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	7.83	3.28	4.02	4.72	5.55	3.45	6.67	3.03	5.06	2.72	4.633
February ..	6.33	2.26	2.27	3.78	4.37	3.43	4.38	3.67	3.11	3.76	3.736
March	.93	4.44	4.24	4.08	4.81	3.85	3.74	6.30	4.67	5.75	4.281
April	3.82	3.60	2.38	3.49	3.93	6.02	2.44	3.60	3.45	3.95	3.668
May	2.75	1.61	3.24	3.38	2.75	2.09	6.99	6.25	4.61	3.41	3.708
June	4.28	3.36	1.73	2.72	1.45	2.70	2.52	8.22	2.97	2.46	3.241
July	2.30	1.13	5.53	5.46	3.19	2.13	3.71	3.55	5.45	9.25	4.170
August	8.53	6.03	4.67	7.26	4.65	7.44	5.42	6.24	4.80	3.69	5.873
September ..	4.11	1.87	1.70	7.49	3.51	3.93	2.25	1.05	8.01	3.53	3.745
October	8.99	6.50	4.30	10.56	3.66	5.47	6.08	7.94	3.01	7.90	6.441
November ..	5.58	8.42	4.92	5.55	5.69	5.89	4.79	6.53	5.66	2.31	5.534
December ..	8.49	6.12	6.38	4.68	4.57	2.79	6.19	7.86	6.40	10.36	6.384
TOTALS ..	63.94	48.62	45.38	63.17	48.13	49.19	55.18	64.24	57.20	59.07	55.414

1907. *Broughton Church*
" *Station*

$1\frac{1}{4}$ mile NW.

1 " NW.

H.B.

RAINFALL at Broughton-in-Furness Orchard RoadCounty of North LancashireObserver C. R. Chamberlay DeserodRiver Basin Duddon + C 1Snowdon Rain Gauge, by N+3

Diameter ...	5										
Height	1	3									
Altitude ...	101										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	5.55	2.39	6.05	5.66							
February ...	7.22	6.84	2.87	2.76							
March	1.94	1.76	8.52	4.61							
April	3.21	3.76	1.19	4.75							
May	2.66	3.09	2.73	3.71							
June	2.80	2.10	6.13								
July	4.60	1.74	4.50								
August	7.42	5.40	7.65								
September ..	1.03	5.64	2.69								
October ...	2.27	4.65	7.22								
November ..	6.07	6.00	6.54								
December ...	7.40	9.63	6.03								
TOTALS ...	52.17	54.00	62.12								
	2	2	2								

712 House 30 ft high 40 ft SE
 1913 found Leech Ruff in May

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
			Broughton	7 1/2 miles	NW	Broughton	1 1/2	NW