

RAINFALL AT *Chorley Withnell Hall*

70

Lat.

Lon.

County of *Lancashire*

Rain Gauge, by

Observer *J. Shackleton Esq*

Diameter...						5	.		.	.		
Height						6	.		.	.		
Altitude						545	.		.	.		
Year	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	MEANS.	
January						4.95	2.08	7.01	3.67	.75		
February....						.94	4.33	4.33	2.20	4.05		
March.....						1.05	3.68	4.17	1.59	2.32		
April						1.12	3.26	2.63	1.67	2.33		
May						2.84	.80	3.74	5.46	2.50		
June						3.82	2.94	2.84	3.81	4.06		
July.....						6.24	4.09	6.62	1.27	6.51		
August						2.57	5.55	6.67	6.66	8.42		
September ..						5.26	4.70	3.68	6.78	3.54		
October						4.87	2.61	3.92	5.70	3.13		
November ..						4.10	4.08	6.97	3.01	1.03		
December ..						1.93	5.19	4.65	2.51	1.47		
TOTALS ..						39.69	43.31	57.23	44.33	40.11		

RAINFALL AT Chorley, Mitchell Hall

80

Lat. _____

Lon. _____

County of

Lancashire

Rain Gauge, by _____

Observer

J. Shackleton, Esq.

Ribble - Douglas 2

Diameter	5											
Height	6								10			
Altitude	545											
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.	
January	1.48	.72	3.50	5.62	4.65	2.14	5.79	2.66	1.81			
February	3.05	5.13	2.19	3.94	4.10	3.46	.88	1.78	.64			
March	2.00	3.29	5.28	1.56	3.72	2.56	2.67	2.47	4.06			
April	2.59	1.22	5.62	2.52	1.07	2.98	2.14	2.02	1.86			
May	2.13	5.86	2.94	.57	2.19	1.75	4.34	2.30	.47			
June	4.10	2.95	5.13	4.80	1.52	3.63	2.54	.88	3.38			
July	6.86	5.22	6.12	2.74	5.41	2.07	5.00	1.79	7.62			
August	2.05	6.35	6.10	2.64	1.59	1.79	2.07	1.89	4.67			
September....	4.74	2.31	2.30	6.56	3.89	4.43	4.67	6.19	1.97			
October	3.83	2.86	3.32	5.18	3.09	5.65	5.68	2.22	2.05			
November....	5.38	4.79	6.57	3.76	1.56	3.21	2.98	2.11	6.41			
December	6.65	5.89	4.29	3.65	5.60	2.40	6.33	2.83	2.73			
TOTALS	44.86	46.59	53.36	43.54	38.39	36.07	45.39	29.14	37.67			

1889 Observer dead