

RAINFALL AT *Mountain Ash Res.*

Lat. Lon. County of *Glamorgan*

Rain Gauge, by Observer *F. Russell*

Inf - 6.

Diameter					5						
Height					2	-					
Altitude											
Year.....	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.
January						7.85	8.14				
February						9.77	1.77				
March						3.12	10.08				
April						5.10	4.61				
May						4.84	6.65				
June						3.60	6.2				
July						1.88	4.11				
August					[#] 1.77	5.34	4.69				
September....					4.38	9.79	5.49				
October					2.39	6.77	11.05				
November....					2.43	9.59	8.25				
December					11.23	3.09	9.56				
TOTALS						70.94	75.02	91.9			

Aberdare Church 4 1/2 miles S. N. 80 W.

3 same as Darnley.

RAINFALL AT

Glydach Reservoir Mountain Ash

Lat. _____

Lon. _____

²

County of

Glamorgan

Rain Gauge, by _____

Observer

J. Williams Esq

Taff - 6.

Diameter				5							
Height				10							
Altitude				937							
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January				4.14	10.83	6.83	2.51	2.48	4.00	14.41	
February				12.15	12.39	.04	1.89	6.70	4.28	6.98	
March				.80	8.79	6.81	9.00	9.01	2.12	3.39	
April				.29	4.24	4.56	1.86	7.21	4.11	7.76	
May				6.10	5.37	1.12	.10	2.43	5.29	5.55	
June				1.52	4.96	1.15	2.70	3.82	3.78	1.80	
July				8.01	6.30	7.86	2.77	3.46	1.23	1.35	
August				6.12	5.55	8.25	2.98	8.92	8.52	3.07	
September....				4.94	3.46	2.33	12.47	7.20	3.33	4.28	
October				8.53	9.99	4.80	8.30	3.86	10.12	7.09	
November....				4.25	10.25	11.77	1.72	7.53	8.73	6.65	
December				11.54	6.95	6.23	14.34	16.98	13.14	5.25	
TOTALS				68.49	89.18	61.75	60.64	79.60	68.65	67.58	

Mountain Ash Station 2 miles N.E.

Pewrhiwceiber " 2.2 " E.N.E.

RAINFALL AT Mountain Ash Ghyll Res

Lat. Lon. County of Glamorgan

Rain Gauge, by Observer J. W. Williams Esq
W. G. Thomas Esq

Sept - 6.

Diameter ..	5										
Height	10										
Altitude ..	937				930						
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	9.82	5.65	4.11	13.18	12.31	3.82	13.33	5.17	5.17	3.49	7.605
February ..	11.99	2.57	3.87	8.23	9.14	1.89	7.15	4.50	4.69	.96	5.499
March	1.31	5.60	3.83	13.51	6.34	13.25	5.96	4.52	7.36	6.66	6.834
April	3.07	8.33	3.51	2.87	5.35	6.35	1.69	4.75	4.40	4.78	4.510
May	4.48	1.99	3.22	5.01	4.83	.39	5.91	4.86	4.81	2.28	3.778
June	5.04	3.87	4.07	1.98	2.61	7.15	3.74	9.32	1.59	4.43	4.380
July	3.37	1.72	2.45	4.05	1.43	1.94	1.76	4.02	6.74	3.64	3.102
August	8.21	4.93	4.80	2.20	6.14	8.80	5.24	6.69	10.48	3.20	6.069
September ..	3.99	5.19	3.98	8.30	5.04	5.90	2.42	2.08	5.69	5.29	4.788
October	11.09	4.90	7.77	21.98	4.17	5.50	13.74	9.81	5.93	14.73	9.962
November ..	9.14	3.72	7.25	9.22	6.96	8.82	7.34	6.22	5.25	3.76	6.768
December ..	15.17	11.58	8.50	9.14	10.83	3.32	4.63	14.42	6.52	14.25	9.839
TOTALS ..	86.68	60.05	57.36	99.67	75.15	67.13	72.91	76.36	68.63	67.40	73.134

1904 Llanwern Church 1 mile NSE
Gwynedd Old Station 3/4 " SE

W. G. Thomas

RAINFALL at Mountain Ash Clydach ResCounty of GlamorganObserver W. L. Thomas EsqRiver Basin Joff 6

Rain Gauge, by _____

Diameter ...	5										
Height	1 0										
Altitude ...	930 ft										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	10.44										
February ...	10.36										
March	2.88										
April	4.09										
May	3.91										
June	7.37										
July	6.19										
August	8.97										
September ...	2.6										
October ...	6.14										
November ...	8.43										
December ...	10.67										
TOTALS ...	79.71	N.A.									

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.