

Station No. 5122/5/5

RAINFALL at *Daer (Yards Craig)*

41

County of *Lanark*Observer *M.S. Neilson Esq. C.E.*River Basin & - *Slade - Right Bank.*Type of Gauge *M.O. 402/46 Mark II (Type Kessum)**1st read by pump engine every 15 min.*

Annual Average in. based on years obs. un-weighted. Period of average Ref.

File No.

Diameter	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	Means
Hoight											
Altitude											
Year	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	Means
January								-100	6.79	5.18	
February								-100	8.33	6.90	
March								(5.72)	2.92	6.99	
April								(10.04)	8.22	5.84	
May								(4.32)	2.24	3.14	2.53
June								6.28	1.35	4.02	
July								3.89	2.35	8.27	
August								8.22	5.14	8.45	
September								6.32	3.05	13.57	
October								(6.44)	7.52	5.17	
November								4.78	8.20	4.60	
December								10.56	12.93	3.18	
TOTALS								-100	69.94	75.30	
								Imp.	3	D	

Inspected by D. + glass pool 28.9.48 11" gauge in earthenware pipe, imploding possible good site on N.E. of Daer Water which will be even better when dam is built above this point. Gauge read weekly + monthly.
 30.9.48 H.O. daily gauge 402/46 Mark II set up. To be surrounded by turf wall.
 7.10.48. Turf wall set up.
 Inspected 12.10.49 by Mr. Thomson. Grass seeds attention. Record should be watched closely as snowbirds are changing owing to dumping of soil in the neighbourhood, and construction materials may be obtained nearby. Water dept. asked to keep watch and inform A.M.O. of anything likely to affect readings.

March + April 48 app. Met 0.4 J

14044

Position of Station on reduced Ordnance Survey Map, 1 mile to 1 inch Series

No. of Map

Reference No.

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge.	Direction from gauge.
1948	55° 21' 59"	3° 36' 58"						

BRITISH RAINFALL ORGANIZATION

Station No. 5162/5/5

51

Observer

County Water Engineer.

of average.....	Ref.....
1916-50	" 5
File No.	

Annual Average.....in. based on.....years obs. un-weighted. Period of average.....Ref.
 " " 71'34 " " " 11 " " 1949-59. " " " 1916-50 " S
 P.E. N.

Insp. ^{Sanjour} ~~St. Charles~~ 22-1-77. Site excellent but gates needs cutting. Prop. R. Larson 7153. Gate too solid. Site V. int. Contractors should be asked to provide change.
 Insp. St. Charles 25/50. Gate sound and correct, but should be fixed horizontal + turf wall requires repairing. Height of dam is increasing + dumps rather near, but site very good.

3rd Karl Wall

National Grid Reference NS(26)976092

Summary of Earlier Records from 10-year Sheets :

(62) Wt. 13072-389 10M 6/50 T.S. 841