

RAINFALL AT *Grimby Inby-on-Humber*

Lat. Lon. County of *Lincoln North*

Rain Gauge, by Observer *H. B. Parker Esq*

Humber - 5.

Diameter ..			5								
Height			10								
Altitude ..			175								
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEAN.
January ..			# 1.00	2.21	1.72	.44	2.96	.83	1.57	.64	
February ..			1.04	.82	2.66	.90	2.72	1.75	1.74	1.19	
March			1.42	2.64	1.85	1.91	1.90	1.26	2.15	3.64	
April			1.49	1.59	.99	1.46	.68	1.98	2.14	1.84	
May			2.98	2.68	1.64	.68	1.66	3.33	2.02	1.24	
June			2.61	2.13	.93	2.75	1.81	2.53	1.58	2.31	
July			2.18	3.04	2.65	1.29	1.21	.99	3.25	4.21	
August			2.25	5.21	5.76	2.97	2.43	2.08	2.05	5.40	
September ..			.49	3.89	2.01	1.47	.62	.56	1.82	1.47	
October			2.46	5.70	.71	2.22	4.38	4.18	1.05	3.18	
November ..			1.36	2.02	1.13	3.01	3.58	2.03	1.48	.80	
December ..			2.33	.78	1.72	.51	2.28	2.33	1.11	4.60	
TOTALS ..			21.71	32.71	23.77	19.64	26.23	23.85	21.96	30.52	

1902 House 20 ft high 42 ft S
 " 24 " " 42 " S.W.
 Building 8 " " 18 " E
 " 9 " " 35 " N
 1906 St. Andrew Ch Inby-on-Humber 300 yards N
 Grimby Station 6 miles E

RAINFALL at Leby. on. HumberCounty of LincolnshireObserver H. B. Parker EsqRiver Basin Humber Right Bank Tributaries 5

Rain Gauge, by _____

Diameter ...	5										
Height	1.0										
Altitude ...	175										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	1.81	1.67	2.94								
February ...	2.22	1.38	1.41								
March	.72	2.40	2.78								
April	1.98	1.22	.19								
May	2.17	.96	2.53								
June	2.18	6.04	5.16								
July	3.05	.78	3.24								
August	3.85	1.79	4.20								
September ..	.40	1.90	2.19								
October ...	2.61	2.09	2.87								
November ..	3.35	3.46	3.42								
December ...	3.15	3.50	2.81								
TOTALS ...	27.49	27.29	33.74								

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.