

RAINFALL AT *Aberdare Treherbert*

Lat.....

Lon.....

County of.....

Glamorgan

Rain Gauge, by.....

Observer.....

W. T. Lewis Esq.

Staff - 6.

Diameter	.5										
Height	1										
Altitude	634		640								
YEAR	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	MEANS.
January.....	7.69	7.28	21.83	18.60	14.66	16.93	8.00	18.24	7.84		
February.....	9.46	8.76	13.09	2.15	8.82	6.33	15.13	9.37	7.40		
March.....	6.01	5.62	7.04	5.97	7.91	4.58	9.97	6.08	4.93		
April.....	2.90	10.07	3.23	1.46	6.65	5.91	8.27	6.55	4.86		
May.....	7.40	6.84	27.47	4.74	1.98	6.68	8.27	7.85	10.75		
June.....	1.11	3.30	9.21	4.15	3.32	9.35	5.45	6.39	4.68		
July.....	3.31	11.56	7.25	8.72	2.98	8.14	4.48	9.70	3.24		
August.....	4.89	4.29	4.10	9.19	12.92	10.86	7.32	11.54	7.78		
September.....	2.50	8.98	11.21	7.63	7.35	8.24	11.24	6.97	4.83		
October.....	16.67	9.11	12.81	9.97	16.01	12.73	11.15	12.41	10.80		
November.....	8.94	1.98	17.17	4.91	5.59	11.97	7.56	17.76	4.20		
December.....	3.73	9.97	15.42	7.10	6.42	8.81	18.39	8.16	3.10		
TOTALS.....	72.61	81.60	126.63	84.59	94.61	110.63	107.78	121.02	74.41	—	

1879 Imp.