

RAINFALL AT Chutonsleigh Eggesford

Lat.....

Lon.....

County of Devon

Rain Gauge, by.....

Observer

M^r. A. Spreadbury

Taw - 2

Diameter.....	8	8									
Height.....	1.2	1.2	1.								
Altitude.....	400	400	400 [↑]								
YEAR.....	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	MEANS.
January.....	1.79	5.95	5.20	2.85	6.45	97	5.16	2.68			
February.....	1.60	4.10	2.70	3.10	1.98	5.23	3.42	1.94			
March.....	3.20	2.96	4.46	1.61	1.61	5.31	3.10	3.24			
April.....	2.99	3.16	1.29	2.07	1.39	3.34	4.00	3.84			
May.....	.05	2.33	1.56	} 1.94	4.11	.18	2.54	5.11			
June.....	3.14	3.38	1.11		3.55	1.39	1.53	2.80			
July.....	4.41	5.54	3.91	1.83	3.34	1.06	3.66	1.96			
August.....	1.80	2.56	6.43	4.18	3.86	3.31	5.44	4.68			
September.....	5.48	3.78	2.26	6.40	5.02	7.32	2.38	3.03			
October.....	4.33	2.82	6.85	3.79	4.41	6.77	2.99	2.53			
November.....	3.34	2.19	5.63	3.33	3.08	6.84	4.55	7.74			
December.....	3.71	3.59	5.44	1.15	5.28	1.65	9.97	3.10			
TOTALS.....		33.06	51.68	37.19	36.75	46.57	45.62	44.60			

1875 No tree within 100 ft of gauge

1878 M^r. Spreadbury has left name is now M^r. Geary