

RAINFALL AT

Deanhead

Lat. _____

Lon. _____

County of Yorks W.B.

Rain Gauge, by _____

Observer ? Dan Drainage Commission

Cuse. Aien & Balder 8

Diameter . . .												
Height	1	0										
Altitude . . .	965											
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.	
January . . .	8.13	2.72	2.93	.90	5.04	3.50	3.23	1.40	4.02	(6.70)		
February . . .	.40	.40	.84	6.50	8.10		1.13	2.20	4.90	(1.50)		
March	5.13	1.90	3.00	3.71	5.22	(3.31)	7.10	6.52	3.07	1.64		
April	1.79	2.74			3.44	3.34	1.95	4.00	3.76	4.57		
May	3.26	4.20	4.88	2.73	3.07	.92	.62	2.16	4.08	5.32		
June	4.27	1.80	4.22	2.57	3.30	3.70	2.75	4.70	4.01	1.15		
July	4.56	3.50	2.96	4.42	4.16	5.84	2.48	1.32	1.33	2.26		
August	6.11	9.62	3.75	3.23	4.61	5.32	2.44	4.17	8.13	3.46		
September . .	1.73	4.73	4.46	5.26	1.10	2.05	10.26	4.50	.50	9.54		
October	5.23	7.75	7.78	5.18	4.64	5.83	6.93	2.50	5.90	4.52		
November . . .	6.72	3.66	3.49	5.82	2.89	5.05	2.07	4.34	2.98	2.75		
December . . .	.40	6.36	2.54	5.68	3.11	5.90	6.19	6.85	6.09	(2.80)		
TOTALS . . .	47.73	49.38	40.85	46.00	48.68	44.76	47.15	44.66	48.77	46.21		

1889 # Aug. 6.96 in, Sept 4.51 in, Oct 6.74 in, Nov. 2.28 in, Dec. 4.93

Many months have been altered for snow. See Oldham Water
Tables 1903

RAINFALL AT

Deanhead

Lat.

Lon.

County of

Yorks W.B.

Rain Gauge, by

Observer

Cuse. June & October 8.

Diameter ..											
Height	1	0									
Altitude ..	965										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	7.32	.00	4.02								
February ..	(5.50)	.10	.70?								
March	.96	1.50	1.45								
April	3.73	.80	2.12								
May	2.04	1.10	3.12								
June	3.23	1.40	2.30								
July	2.32	2.22	2.92								
August	(5.81)	1.26	2.32								
September ..	1.32	.20	2.23								
October	3.76	3.42	4.94								
November ..	1.53	3.55	2.00								
December ..	(6.53)	.60									
TOTALS ..	44.05	16.15									

1901+2 Utterly bad; gauge kept indoors and put out from time to time when it rained.