

RAINFALL AT Greenock Shaws N. W. Glenbrae No. 6

Lat.

Lon. County of. *Renfrew.*

Rain Gauge, by. Observer

Clyde, L. bank - 7.

Diameter		6									
Height		0.9					1.			.9	
Altitude		573.9		574.							
YEAR	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	MEANS.
January.....			11.60	11.90	9.60	10.60	6.00	11.30	7.90	2.00	
February			7.50	1.70	2.30	2.60	7.00	6.70	4.00	3.10	
March			5.10	3.00	6.10	2.60	7.10	4.20	3.10	7.10	
April.....		*	2.00	.50	3.70	2.50	3.30	5.50	3.70	2.50	
May			1.60	3.50	4.10	2.40	4.10	.90	4.00	5.40	3.00
June.....			3.00	8.20	3.30	1.90	3.50	5.00	5.90	3.90	6.10
July			4.10	4.80	6.20	3.50	2.50	3.70	5.80	1.20	5.10
August.....			5.00	5.00	7.20	6.20	4.80	7.20	10.00	3.80	6.20
September....			3.40	11.40	8.50	8.80	5.30	3.80	2.90	6.70	10.60
October.....			7.30	6.00	9.00	12.20	8.60	8.60	10.10	9.60	3.80
November.....			4.70	10.80	5.70	6.00	6.30	3.20	12.70	2.70	2.30
December.....			9.00	9.10	6.80	2.30	7.10	10.40	10.80	2.40	5.40
TOTALS			85.00	67.90	65.00	60.50	66.20	89.90	54.40	57.20	

C

RAINFALL AT *Greenock Glenbrae*

Lat. _____

Lon. _____

 County of *Perth*

Rain Gauge, by _____

 Observer *J. H. Lyon, Esq., C.E.*
Clyde, L. bank - 2.
No 7

Diameter	6											
Height	0.9											
Altitude	574 ft											
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.	
January	4.70	.80	7.60	8.80	10.20	6.80	6.00	6.40	6.40			
February	7.20	5.23	5.20	8.90	8.40	7.00	2.70	5.90	1.80			
March	4.50	5.69	6.50	3.00	3.80	5.10	4.90	2.60	4.80			
April	5.00	3.23	3.10	3.60	2.40	3.70	3.80	3.80	3.50			
May	1.90	4.15	3.10	3.60	5.20	3.70	4.40	1.60	6.80			
June	2.80	7.18	4.80	2.70	1.30	1.80	1.90	2.00	3.60			
July	3.90	6.33	7.70	3.60	7.40	3.00	4.10	4.90	7.20			
August	2.30	5.68	3.80	6.20	3.30	3.70	3.80	4.50	5.20			
September	3.80	3.90	5.00	3.90	5.30	9.50	8.50	6.50	3.10			
October	.80	3.62	5.50	7.50	7.90	5.10	5.50	4.30	3.70			
November	9.40	9.72	9.10	10.20	6.10	4.60	6.70	5.80	9.70			
December	6.40	9.40	7.60	8.10	10.50	4.20	6.20	6.00	7.70			
TOTALS	52.70	64.93	70.00	71.10	71.80	57.40	58.50	54.30	63.50			