

RAINFALL AT Manchester Salford

80

Lat. _____ Lon. _____ County of Lancashire
 Rain Gauge, by _____ Observer A. Royle Esq C.E.

Mossy Upper H.

Upper											
Diameter		5									
Height		1. -									
Altitude		86 π									
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.
January		63	2.25	3.77	3.95	1.77	4.59	2.08	1.45	1.13	
February		5.04	2.05	1.54	1.77	2.41	76	.50	.95	1.92	
March		3.60	2.05	.97	1.86	2.01	2.08	1.61	1.42	2.34	
April		1.12	3.42	1.76	.61	1.21	1.58	1.24	1.66	2.17	
May		3.67	1.70	.79	1.33	1.88	5.16	2.13	.70	2.38	
June		1.92	5.51	3.68	.84	3.06	1.88	1.14	2.81	1.03	
July		2.72	6.14	2.75	2.77	1.22	4.69	1.01	5.46	2.85	
August		5.31	2.90	2.94	1.86	1.26	2.58	1.15	2.86	5.16	
September....		2.19	1.60	5.13	2.95	4.63	3.37	3.53	1.42	2.47	
October		2.57	3.35	5.16	1.98	5.65	4.78	2.00	1.64	2.41	
November....		2.69	5.16	3.13	1.58	2.75	2.07	1.00	4.57	2.01	
December		3.78	3.69	2.33	3.31	2.19	4.14	2.23	2.18	2.26	
TOTALS		352.4	40.88	33.95	24.81	30.04	37.68	19.62	27.12	28.13	

St. Matthews 2/3 mile SW
Open paling 6 ft high 12 ft SW

RAINFALL AT *Manchester Streetford*

Lat. _____

Lon. _____

County of *Lancashire*

Rain Gauge, by _____

Observer *H Royle Esq C.E.*

Stat. Messing - Upper H

Diameter	5											
Height	10											
Altitude	86 ft											
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS	
January	3.07	2.29	3.28	1.44	2.21	2.86	1.05	1.73	1.77	3.63	2.223	
February	.44	.20	2.50	3.28	4.02	.34	2.11	2.48	2.03	1.12	1.852	
March	2.49	1.65	1.12	.56	2.57	3.01	3.56	2.53	.98	1.80	2.027	
April	.78	2.37	1.10	.68	1.91	1.86	1.65	2.45	2.17	2.85	1.782	
May	1.99	2.51	3.17	1.83	1.90	.76	.50	1.89	3.28	2.63	2.046	
June	3.21	2.65	3.98	1.15	3.02	2.15	2.95	3.60	2.62	2.19	2.752	
July	2.80	2.23	3.16	2.36	3.54	5.10	2.01	1.62	.77	1.42	2.501	
August	4.01	5.32	4.58	2.65	3.91	3.08	2.69	2.84	5.67	1.46	3.621	
September...	.68	3.10	3.96	3.21	1.21	1.66	5.95	3.97	.58	5.00	2.932	
October	2.38	3.88	4.04	3.16	3.59	3.33	3.91	2.04	3.48	3.32	3.213	
November...	5.00	2.56	2.48	2.08	1.80	2.95	1.27	4.55	1.99	1.14	2.582	
December ...	.46	5.31	2.21	3.36	2.45	3.85	3.56	3.34	3.71	2.73	3.098	
TOTALS	27.31	34.07	35.58	25.76	32.13	30.95	31.21	33.04	29.05	29.29	20.839	

1890. *P. Matthews* 2 3/4 mile SW
open palmjs 6 ft high 12 ft SW

RAINFALL AT

Manchester Streetford

Lat.

Lon.

County of Lancashire South

Rain Gauge, by

Observer

H. Royle Esq. Ch.

Small 5 Inersay H.

Diameter ..	5										
Height	10										
Altitude ..	86 ft										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	4.24	2.08	2.41								
February ..	2.98	1.44	1.19								
March	.70	2.12	1.60								
April	2.09	2.11	2.33								
May	1.78	.88	3.26								
June	3.17	2.17	1.43								
July	2.60	3.10	2.22								
August	5.40	1.60	3.07								
September..	1.27	.86	1.10								
October	4.99	2.92	3.74								
November ..	1.92	3.36	1.68								
December ..	4.37	4.41	2.30								
TOTALS ..	35.51	27.05	26.33								

1900 St Matthews Church 2 1/2 mile S.W.

Palings 6 ft high 12 ft S.W.

1902 October 5th gauge moved 1 mile E