
Long Duration Compressor Test

- -Compressor was turned on March 3rd at approximately 2pm.
- -Cabinet was kept at ~0% humidity for the entire time the compressor was left on.



Cabinet Humidity Flow Rate Tests

On the next slide

- -Tested 3 different flow rates for air into the cabinet, with 2 runs for each flow rate.
- -The difference between 100% and 50% flow rate did not double the time needed for the cabinets to reach 0% humidity.
- -The 5% flow rate resulted in an increase of 15% from the 100% flow rate test.

