Facility Name: BUHLER

EPA Facility Identifier: 1000 0010 5502 Plan Sequence Number: 1000085602

# **Section 1. Registration Information**

#### Source Identification

Facility Name: BUHLER

Parent Company #1 Name: MID KANSAS COOPERATIVE

**ASSOCIATION** 

Submission Type: Resubmission Receipt Date: February 2020

**Facility Identification** 

Facility ID: 1000 0010 5502

**Dun and Bradstreet Numbers (DUNS)** 

Facility DUNS: N/A

**Facility Location Address** 

 Street 1:
 101 S MAIN

 Street 2:
 N/A

 City:
 BUHLER

 State:
 KS

 ZIP:
 67522

 ZIP4:
 N/A

 County:
 Reno

Facility Latitude and Longitude

Latitude (decimal): 38.129970 Longitude (decimal): -097.764485

Local Emergency Planning Committee and Regulations

LEPC: Reno County LEPC

 OSHA PSM:
 N/A

 EPCRA 302:
 Yes

 CAA Title V:
 N/A

Facility Name: BUHLER

EPA Facility Identifier: 1000 0010 5502 Plan Sequence Number: 1000085602

#### **Process Chemicals**

Program Level: Program Level 2 process
Chemical Name: Ammonia (anhydrous)
CAS Number: 7664-41-7

CAS Number: 7664-41Flammable/Toxic: Toxic

### **Process NAICS**

NAICS Code: 42491

NAICS Description: Farm Supplies Merchant Wholesalers

### **Section 6. Accident History**

No records found.

## **Section 9. Emergency Response**

### Written Emergency Response (ER) Plan

regulated substance(s)?):

health care?):

Community Plan (Is facility included in Yes written community emergency response plan?):

Facility Plan (Does facility have its own W/A written emergency response plan?):

Response Actions (Does ER plan N/A include specific actions to be taken in response to accidental releases of

Public Information (Does ER plan N/A include procedures for informing the public and local agencies responding to accidental release?):

Healthcare (Does facility's ER plan N/A include information on emergency

### Local Agency

Agency Name (Name of local agency with which the facility ER plan or response activities are coordinated):

Agency Phone Number (Phone number of local agency with which the facility ER plan or response activities are coordinated):

BUHLER FIRE DPARTMENT

(620) 694-2735