Section 1. Registration Information

Source Identification

Facility Name: Honeywell International Inc., Geismar

Plant

Parent Company #1 Name: Honeywell International Inc.

Submission Type: Resubmission
Receipt Date: February 2022

Facility Identification

Facility ID: 1000 0008 5061

Dun and Bradstreet Numbers (DUNS)

Facility DUNS: 41519067

Facility Location Address

 Street 1:
 P.O. Box 226

 Street 2:
 5525 Highway 3115

 City:
 Geismar

 State:
 LA

 ZIP:
 70734

 ZIP4:
 N/A

 County:
 Ascension

Facility Latitude and Longitude

Latitude (decimal): 30.228335 Longitude (decimal): -091.053827

Local Emergency Planning Committee and Regulations

LEPC: Ascension Parish LEPC

OSHA PSM: Yes
EPCRA 302: Yes
CAA Title V: Yes

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Process Chemicals

Program Level: Program Level 3 process

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

CAS Number: 7664-39-3 Flammable/Toxic: Toxic

Program Level: Program Level 3 process

Chemical Name: Oleum (Fuming Sulfuric acid) [Sulfuric

acid, mixture with sulfur trioxide]

CAS Number: 8014-95-7 Flammable/Toxic: Toxic

Program Level: Program Level 3 process
Chemical Name: Trifluorochloroethylene [Ethene,

chlorotrifluoro-]

CAS Number: 79-38-9
Flammable/Toxic: Flammable

Program Level: Program Level 3 process
Chemical Name: Vinylidene fluoride [Ethene,

1,1-difluoro-]

CAS Number: 75-38-7
Flammable/Toxic: Flammable

Program Level: Program Level 3 process

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

CAS Number: 7664-39-3 Flammable/Toxic: Toxic

Program Level: Program Level 3 process
Chemical Name: Chloroform [Methane, trichloro-]

CAS Number: 67-66-3 Flammable/Toxic: Toxic

Program Level: Program Level 3 process

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Program Level: Program Level 3 process

Chemical Name: Chlorine
CAS Number: 7782-50-5
Flammable/Toxic: Toxic

Program Level: Program Level 3 process

Chemical Name: Hydrochloric acid (conc 37% or greater)

CAS Number: 7647-01-0 Flammable/Toxic: Toxic

Program Level: Program Level 3 process

Chemical Name: Boron trifluoride [Borane, trifluoro-]

CAS Number: 7637-07-2 Flammable/Toxic: Toxic

Program Level: Program Level 3 process

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

CAS Number: 7664-39-3 Flammable/Toxic: Toxic

Process NAICS

NAICS Code: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

NAICS Code: 325211

NAICS Description: Plastics Material and Resin

Manufacturing

NAICS Code: 325199

NAICS Description: All Other Basic Organic Chemical

Manufacturing

Section 6. Accident History

Accident History ID: Accident 1

Date of Accident: January 2024

Time Accident Began (HH:MM): 01:00
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 45 Minutes

Release Event

Gas Release:YesLiquid Spill/Evaporation:N/AFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: Yes Process Vessel: N/A Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 16.0
Units: Miles/h
Direction: NE
Temperature: 60
Atmospheric Stability Class: B
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 0
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 152
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: N/A Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes N/A Revised Maintenance: Revised Training: N/A Revised Operating Procedures: N/A New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 45
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 2

Date of Accident: January 2023

Time Accident Began (HH:MM): 20:10
NAICS Code of Process Involved: 325199

NAICS Description: All Other Basic Organic Chemical

Manufacturing

Release Duration: 001 Hours 04 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:N/AFire:N/AExplosion:YesUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: Yes Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 1.0
Units: Miles/h
Direction: W
Temperature: 53
Atmospheric Stability Class: B
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths:

Public Responder Deaths:

O
Public Deaths:

Employee or Contractor Injuries:

Public Responder Injuries:

O
Public Injuries:

O
On-Site Property Damage (\$):

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 95
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: Yes Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: Yes Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes Revised Maintenance: Yes Revised Training: N/A Revised Operating Procedures: N/A **New Process Controls:** N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 871
Percent Weight: 19

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

CAS Number: 7664-39-3 Flammable/Toxic: Toxic

Quantity Released (lbs):1684Percent Weight:37Chemical Name:ChlorineCAS Number:7782-50-5Flammable/Toxic:Toxic

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 3

Date of Accident: December 2022

Time Accident Began (HH:MM): 07:50
NAICS Code of Process Involved: 325199

NAICS Description: All Other Basic Organic Chemical

Manufacturing

Release Duration: 003 Hours 10 Minutes

Release Event

Gas Release:YesLiquid Spill/Evaporation:N/AFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: N/A Transfer Hose: N/A Valve: N/A Pump: N/A Joint: Yes Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 8.6
Units: Miles/h
Direction: NW
Temperature: 60
Atmospheric Stability Class: C
Precipitation Present: Yes
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 0
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 229
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: Yes Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: Yes Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes Revised Maintenance: Yes Revised Training: N/A Revised Operating Procedures: N/A New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 46
Percent Weight: 86

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 4

Date of Accident: December 2022

Time Accident Began (HH:MM): 10:15
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 10 Minutes

Release Event

Gas Release:YesLiquid Spill/Evaporation:N/AFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: Yes Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 7.9
Units: Miles/h
Direction: SSE
Temperature: 62
Atmospheric Stability Class: B
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 0
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 509
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: N/A Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** Yes By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes Revised Maintenance: Yes Revised Training: N/A Revised Operating Procedures: N/A New Process Controls: Yes New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 48
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 5

Date of Accident: December 2022

Time Accident Began (HH:MM): 13:20
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 35 Minutes

Release Event

Gas Release:YesLiquid Spill/Evaporation:N/AFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: Yes Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 9.0
Units: Miles/h
Direction: E
Temperature: 72
Atmospheric Stability Class: B
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 0
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 75
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: Yes Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** Yes By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: N/A New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: Yes Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 36
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 6

Date of Accident:

Time Accident Began (HH:MM):

NAICS Code of Process Involved:

325199

NAICS Description: All Other Basic Organic Chemical

Manufacturing

Release Duration: 001 Hours 30 Minutes

Release Event

Gas Release:YesLiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: Yes Process Vessel: N/A Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 6.0
Units: Miles/h
Direction: SW
Temperature: 91
Atmospheric Stability Class: B
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 0
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 536
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: Yes Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: Yes Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: Yes Revised Training: Yes Revised Operating Procedures: N/A New Process Controls: Yes New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 153
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 7

Date of Accident: October 2021
Time Accident Began (HH:MM): 10:50

NAICS Code of Process Involved: 325199

NAICS Description: All Other Basic Organic Chemical

Manufacturing

Release Duration: 000 Hours 01 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: Yes Process Vessel: N/A Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 0.1
Units: Miles/h
Direction: NE
Temperature: 83
Atmospheric Stability Class: D
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 1
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 0
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: Yes Human Error: Yes Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** Yes By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor:

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: Yes New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced:

Chemicals in Accident History

Quantity Released (lbs): 18
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 8

Date of Accident: September 2021

Time Accident Began (HH:MM): 01:30
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 01 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: Yes Transfer Hose: N/A Valve: Yes Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 3.0
Units: Miles/h
Direction: E
Temperature: 75
Atmospheric Stability Class: D
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site	e Impacts
	Jilipaolo

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 1
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Human Error

Contributing Factors

Equipment Failure: N/A Human Error: Yes Improper Procedures: Yes N/A Overpressurization: **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: Yes Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified:

No, not notified

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: Yes New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None:

Other Changes Introduced: Changes to the process design are

under consideration.

Chemicals in Accident History

Quantity Released (lbs): 1
Percent Weight: 49

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

Accident History ID: Accident 9

Date of Accident: May 2021
Time Accident Began (HH:MM): 17:45
NAICS Code of Process Involved: 325998

NAICS Description: All Other Miscellaneous Chemical

Product and Preparation Manufacturing

Release Duration: 000 Hours 03 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: N/A Transfer Hose: N/A Valve: Yes Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 8.0
Units: Miles/h
Direction: N
Temperature: 80
Atmospheric Stability Class: D
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 1
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: Yes Human Error: Yes Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: Yes New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None:

Other Changes Introduced: Changes to configuration are under active consideration. Evaluated

active consideration. Evaluated required PPE and materials of construction of valve. Completed knowledge share across the site.

Chemicals in Accident History

Quantity Released (lbs): 4
Percent Weight: 5

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

Accident History ID: Accident 10

Date of Accident: March 2020
Time Accident Began (HH:MM): 20:14
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 01 Minutes

Release Event

Gas Release:YesLiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: N/A Process Vessel: N/A Transfer Hose: Yes Valve: Yes Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 7.0
Units: Miles/h
Direction: NE
Temperature: 70
Atmospheric Stability Class: D
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site	e Impacts
	Jilipaolo

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 1
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Human Error

Contributing Factors

Equipment Failure: N/A Human Error: Yes Improper Procedures: Yes Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified:

No, not notified

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: Yes New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 1
Percent Weight: 10

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

Accident History ID: Accident 11

Date of Accident: April 2019
Time Accident Began (HH:MM): 09:30
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 01 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: Yes Process Vessel: N/A Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 3.7
Units: Miles/h
Direction: N
Temperature: 66
Atmospheric Stability Class: D
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 1
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Human Error

Contributing Factors

Equipment Failure: N/A Human Error: Yes Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: Yes Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified and Responded

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: Yes New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: Yes Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 31
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 12

Date of Accident: May 2017
Time Accident Began (HH:MM): 20:31
NAICS Code of Process Involved: 325199

NAICS Description: All Other Basic Organic Chemical

Manufacturing

Release Duration: 000 Hours 12 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

 Storage Vessel:
 N/A

 Piping:
 N/A

 Process Vessel:
 N/A

 Transfer Hose:
 N/A

 Valve:
 N/A

 Pump:
 N/A

 Joint:
 N/A

Other Release Source: Sample valve

Weather Conditions at the Time of Event

Wind Speed: 24.0
Units: Miles/h
Direction: S
Temperature: 68
Atmospheric Stability Class: E
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 2
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Equipment Failure

Contributing Factors

Equipment Failure: N/A Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: Notified Only

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: Yes Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: Yes New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 42
Percent Weight: 100

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

EPA Facility Identifier: 1000 0008 5061 Plan Sequence Number: 1000099702

Accident History ID: Accident 13

Date of Accident: May 2017
Time Accident Began (HH:MM): 20:00
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 01 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

 Storage Vessel:
 N/A

 Piping:
 N/A

 Process Vessel:
 N/A

 Transfer Hose:
 N/A

 Valve:
 N/A

 Pump:
 N/A

 Joint:
 N/A

Other Release Source: Shipping trailer overfill line

Weather Conditions at the Time of Event

Wind Speed: 27.0
Units: Miles/h
Direction: ENE
Temperature: 75
Atmospheric Stability Class: E
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 1
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Human Error

Contributing Factors

Equipment Failure: N/A Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** Yes By-Pass Condition: N/A Maintenance Activity/Inactivity: N/A Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified:

No, not notified

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: N/A New Process Controls: Yes New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 1
Percent Weight: 49

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

Accident History ID: Accident 14

Date of Accident: April 2017
Time Accident Began (HH:MM): 22:30
NAICS Code of Process Involved: 32518

NAICS Description: Other Basic Inorganic Chemical

Manufacturing

Release Duration: 000 Hours 01 Minutes

Release Event

Gas Release:N/ALiquid Spill/Evaporation:YesFire:N/AExplosion:N/AUncontrolled/Runaway Reaction:N/A

Release Source

Storage Vessel: N/A Piping: Yes Process Vessel: N/A Transfer Hose: N/A Valve: N/A Pump: N/A Joint: N/A Other Release Source: N/A

Weather Conditions at the Time of Event

Wind Speed: 30.0
Units: Miles/h
Direction: WSW
Temperature: 62
Atmospheric Stability Class: E
Precipitation Present: N/A
Unknown Weather Conditions: N/A

On-Site Impacts

Employee or Contractor Deaths: 0
Public Responder Deaths: 0
Public Deaths: 0
Employee or Contractor Injuries: 1
Public Responder Injuries: 0
Public Injuries: 0
On-Site Property Damage (\$): 0

Known Off-Site Impacts

Deaths: 0
Hospitalizations: 0
Public Deaths: 0
Other Medical Treatments: 0
Evacuated: 0
Sheltered-in-Place: 0
Off-Site Property Damage (\$): 0

Environmental Damage

Fish or Animal Kills:

Tree, Lawn, Shrub, or Crop Damage:

N/A

Water Contamination:

N/A

Soil Contamination:

N/A

Other Environmental Damage:

N/A

Initiating Event

Initiating Event:

Human Error

Contributing Factors

Equipment Failure: N/A Human Error: N/A Improper Procedures: N/A Overpressurization: N/A **Upset Condition:** N/A By-Pass Condition: N/A Maintenance Activity/Inactivity: Yes Process Design Failure: N/A Unsuitable Equipment: N/A Unusual Weather Condition: N/A Management Error: N/A Other Contributing Factor: N/A

Off-Site Responders Notified

Off-Site Responders Notified: No, not notified

Changes Introduced as a Result of the Accident

Improved or Upgraded Equipment: N/A Revised Maintenance: N/A Revised Training: Yes Revised Operating Procedures: N/A New Process Controls: N/A New Mitigation Systems: N/A Revised Emergency Response Plan: N/A Changed Process: N/A Reduced Inventory: N/A N/A None: Other Changes Introduced: N/A

Chemicals in Accident History

Quantity Released (lbs): 1
Percent Weight: 10

Chemical Name: Hydrogen fluoride/Hydrofluoric acid

(conc 50% or greater) [Hydrofluoric

acid]

Section 9. Emergency Response

Written Emergency Response (ER) Plan

Community Plan (Is facility included in written community emergency response plan?):

Yes

Facility Plan (Does facility have its own written emergency response plan?):

Yes

Response Actions (Does ER plan include specific actions to be taken in response to accidental releases of regulated substance(s)?):

Yes

Public Information (Does ER plan include procedures for informing the public and local agencies responding to accidental release?):

Yes

Healthcare (Does facility's ER plan include information on emergency health care?):

Yes

Local Agency

Agency Name (Name of local agency with which the facility ER plan or response activities are coordinated):

Ascension Parish LEPC

Agency Phone Number (Phone number of local agency with which the facility ER plan or response activities are coordinated):

(225) 621-8360