




$U_1 = \text{OPA 347}$

$V_{CC} = 5V$

$R_1 = 27 \text{ k}\Omega$


$R_2 = 560 \Omega$


$R_3 = 1,5 \text{ M}\Omega$

$C_1 = 2,2 \mu\text{F}$

$C_2 = 1 \text{ nF}$

$R_4 = 330 \Omega$





$$R_1 = 82 \, \Omega$$

$$C_1 = 100 \text{ nF}$$

$$C_2 = 100 \text{ nF}$$

