
Plot 2: Sequential Execution Timeline — Thermal Drift & Temporal Stability Inspection
Tests whether MCU warm-up causes latency drift across 50 consecutive repetitions. Dotted line = linear regression slope.
CTRU-LIGHT [Assembly -O3 across 50 consecutive runs]
KYBER512 [Assembly -O3 across 50 consecutive runs]
ECDH [Assembly -O3 across 50 consecutive runs]
KeyGen
Encaps
Decaps
Latency (ms)
Trial Sequence (Repetition Index 1 to 50)