timestamn		joint angle	joint velocity	inint torous	intervention	description	costs technician
					Replaced motor for joint 2	description Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	488.78 Julia Rogers
2023-10-18 1					Cleaned dust from sensors		-
						Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	22.74 Deanna Smith
2023-10-19 2			-21.12172008		Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	20.77 Gregory Morton II
					-9	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	27.79 Mark Austin
2024-01-05 1	13:33:51	62.2154854	-53.60449201	-41.21588271	Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	255.19 Roy Ewing
2023-11-14 1	19:26:28	110.5400794	8.239965944	48.56939562	Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	217.45 Karen Elliott
2022-10-29 2	21:32:29	-62.94686869	-31.69103928	28.08650009	Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	22.27 Andrew Trevino
2023-09-12 1	11:17:49	109.3970871	8.805278984	-11.50262522	Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	124.64 Emily Simpson
2024-03-22	9:19:59	-28 75457804	-23.71361298	-5 531013422	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	210.94 Nancy Gordon
		-146 1463889			Recalibrated torque settings	Intervention: Recalibrated formus settings. Performed a comprehensive check and recalibrated all parameters to ensure online) performance. Documented all changes in the system tog and verified correct operation post-intervention.	129 18 Alan Cabrera
			-59.34505414		Adjusted joint velocity parameters	Intervention. Adjusted joint velocity parameters. Performed a comprehensive check and recalibilitied all parameters to ensure optimal performance. Documented all changes in the system log and vertical covered operation post-intervention.	75.55 Diane Roberts
		-79.80223119				Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	66.86 Eric Mcdowell
2022-08-14 1	14:43:51	24.23517546	-47.84966175	-43.36883797	Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	218.25 Richard Vargas
2023-03-28 2	21:50:49	118.6128028	88.82110775	6.250806712	Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	47.85 Donna Hill
2024-05-17 2	21:31:46	-61.49749487	-83.03070137	-23.8541177	Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	66.43 James Knight
2022-06-26 2	20:03:10	127 9003474	-55 41240338	24 997101	Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	48 66 Frin Williams
2023-08-08	8-08-27	-28.05742439	90.2766799		Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	295.28 Amber Smith MD
			-85 61458038		Undated control software	Intervention: Updated control software: Performed a comprehensive check and recalibrated all parameters to ensure online in control software. Performed a comprehensive check and recalibrated all parameters to ensure online in control software. Performed a comprehensive check and recalibrated all parameters to ensure online in control software.	133 47 Curtis Tucker
		-107.5871217			Routine check-up	Intervention. Spatial control solvings or entire the control s	81.74 Kara Cook
		-114.844849				Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	101.41 John Diaz
2023-05-04	4:29:56	58.27948928	67.25617613	24.55007425	Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	93.28 Jennifer Small
2023-03-25 2	22:28:27	159.9062659	99.21809886	34.39995423	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	224.83 Grant Smith
2022-05-31 1	15:28:16	-148.2483848	-68.36670348	-3.029698461	Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	208.84 Joseph Hanson
					Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	379.11 Kirk Cameron
			-56.77020872		Replaced motor for joint 2	Intervention. Repealed motor for joint 2. Performed a comprehensive check and reclaimable and parameters to ensure optimal performance. Documented all changes in the system log and vertified context operation post-intervention.	261.66 Scott Brown
		-75 52615115				intervention. Celared dust from sensors. Performed a comprehensive check and recalculated as parameters to ensure optimal performance. Documented at continuent on any enterior to creat optimal performance. Documented at continuent of a co	16 2 Randy Garcia
		77.28302781			Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	95.37 Christopher Porter
						Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	27.32 Michael Lewis
2023-03-29 2	21:17:45	124.6089299	88.50264242	28.14063137	Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	53.31 Thomas Jensen
2022-11-07 1	15:38:49	88.29859093	-18.01692256	-18.55500575	Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	55.28 Malik Wolfe
2022-07-02		49.34591976			3	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	9915.24 Kendra Santana
					Replaced damaged end effector	intervention. Repeated damaged end effector, Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system to grate optimal personnance and an extra comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system to grate optimal personnance and performance and performanc	305.15 Stephen Mcdowell
			-95.40544171		Updated control software	intervention. Replaced control Solded control Solde	127.82 Laura Fisher
		-134.2465666	-95.40544171 80.8285832			intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Updated control software. Performance a comprehensive check and recalibrated all parameters in ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention Replaced entire recollished demanace) Performed a comprehensive check and recalibrated all parameters in ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	127.82 Laura Fisher 7773.89 Charles Johns
2023-03-22	6:04:11	16.50650919	96.34051481	-37.38084408	Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	65.89 Frances Padilla
2022-07-20 1	16:33:53	-151.3142734	20.62642244	4.453020556	Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	89.73 Jesus Chen
2023-09-08 2	22:23:24	80.95991833	86.72378888	-18.36361329	Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	141.37 Latoya Benjamin
2023-01-13	1-15-13	165 0891477	40.34768285	-6 928476152	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	212.12 Jerry Sanders
2023-03-18		-122.429143			Replaced motor for joint 2	Intervention. Replaced motor for ionit 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system to and verified correct operation post-intervention.	234.06 Andrew Klein
2020 01 10 1	L. 14.L4	0.020004401	00.44007040	20.0000000	reduction up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	71.81 Ralph Hall
2023-06-16 1		68.809109			Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	389.24 Angela Johnson
		34.12382062	68.9143333			Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	324.83 Charles Wall
2024-02-15	1:52:55	-89.22403038	-74.33076424	14.91740836	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	235.04 John Miller
2022-08-10	9:10:47	-81.23355252	55.05934248	15.4261864	Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	109.48 Gregory Jones
2023-03-20	8-00-36	16 27067497	-71.82787938	10 3030303	Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	265.44 Michael Cooke
						Intervention. Adjusted ioint velocity arameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system loa and verified correct operation post-intervention.	120.84 Ashley Davis
		33.34841678			Routine check-up		51.02 Ms. Sherry Sheppard
						Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	
2020 00 10 1	0.40.40	0.002200140	-31.29642881		Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	84.71 Joseph Harris
2023-08-30 2	22:08:08	-77.6694043	-27.05390477	-28.77667025	Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	28.4 Joel Black
2022-09-03 1	12:56:16	-150.8077254	-54.62828628	8.154269951	Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	161.62 Stephanie Ward
2022-12-25 1	15:24:56	-43.35270267	43.78896621	5.687450411	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	156.05 Danielle Gonzalez
2022-12-11 1	19:41:03	-58 44830352	-18 21288397	34 00104251	Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	242 16 Susan Downs
2024 02 00 1	12-17-20	131 1000405	-63.60729171	4 01645373	Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	489.12 Tasha Long
						intervention. Replaced camaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure opinial performance. Documented all changes in the system og and verified correct operation post-intervention. Intervention Replaced chanaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure opinial performance. Documented all changes in the system og and verified correct operation post-intervention. Intervention Replaced chanaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure opinial performance. Documented all changes in the system og and verified correct operation post-intervention.	305.17 Jonathan Colon
2024-05-07 1		139.5919771	56.07171315		Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	91.77 Robert Wilson
			-7.116630376	40.001 £0001	Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	381.38 Kendra Graham
		56.33147822			Tightened loose bolts on base	Intervention: Tightened loose bolls on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	30.14 Autumn Allen
2024-05-12	9:04:05	68.61092827	-76.51778131	-25.04327414	Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	8637.44 Mrs. Andrea Walters DVM
2022-06-27	4:26:26	-85.71417624	32.22596444	36.28149482	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	218.41 Brittany Luna
2023-09-17	8:52:05	24.72077187	-91.76259114	3.468592497	Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	92.5 Brian Shah
					Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	75.44 Donald Martinez
			90.17620036			intervention. Notation devi-up. Personned a Comprehensive disease and recardance as plan american to entere to enter	137.47 Donna Gibson
		93.58285767	12.46454392			Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	58.87 Emily Shaw
		-86.19113417	68.7205993		Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	97.39 Kristina Harrison
2023-02-26	6:28:13	84.93919514	35.65596761	25.77989914	Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	37.8 Michele Moore
2022-06-24	9:17:45	79.08785178	-8.949672428	-2.747455326	Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	22.1 Jason Barker
2023-11-24	0:16:30	173.3697939	17.29008626	-10.70176043	Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6985.21 Eric Wilson
					Recalibrated torque settings	Intervention. Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system on and verified correct operation post-intervention.	69 Mark Cole
			-97.26212272		Tightened loose bolts on base		39.96 Susan Duncan
					3	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	
			50.78566213		Tightened loose bolts on base	Intervention: Tightened loose bolls on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	36.28 Taylor Bell
2022-10-26 2		-129.7146104	26.32108849		Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	27.36 John Reed
			-28.03181475	43.76664701	Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	5563.74 Paul Thomas
		-6.913820043	-11.7783298	6.268063657	Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	112.65 Linda Schroeder
	4:07:28	445 0044005	63.43182852		Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	427.91 Timothy Compton
2022-09-16					Replaced motor for joint 2	Intervention. Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system los and verified correct operation post-intervention.	381.56 Michael Farmer
2022-09-16 2023-03-01 1	18:45:18		-35 8248720	55.5004Z 147		intervention. Replaced motion to juni 2. Ferrormed a comprehensive check and recalizated all parameters to ensure upmain personned. Deciminate vention and all parameters to ensure upmain personned and changes in the system log and vention operation post-intervention. Intervention: Therefore loose boths on base. Performed a comprehensive check and recalizated all parameters to ensure upmain personned and p	34.11 Tammy Henry
2022-09-16 2023-03-01 1 2022-07-01 1	18:45:18 11:49:37	-76.82539022	-35.8248739	42 6244224			
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1	18:45:18 11:49:37 18:44:12	-76.82539022 -160.6243519	53.94623794				
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2	18:45:18 11:49:37 18:44:12 22:59:55	-76.82539022 -160.6243519 124.5557174	53.94623794 72.26687673	-9.647640652	Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	12.21 Lawrence Jones
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2 2023-03-01	18:45:18 11:49:37 18:44:12 22:59:55 0:25:19	-76.82539022 -160.6243519 124.5557174 96.62999518	53.94623794 72.26687673 -14.00267745	-9.647640652 0.75050164	Cleaned dust from sensors Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	18.35 Cameron Turner
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2	18:45:18 11:49:37 18:44:12 22:59:55 0:25:19	-76.82539022 -160.6243519 124.5557174	53.94623794 72.26687673 -14.00267745	-9.647640652 0.75050164	Cleaned dust from sensors Cleaned dust from sensors		
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2 2023-03-01 2022-07-30 1	18:45:18 11:49:37 18:44:12 22:59:55 0:25:19 10:34:51	-76.82539022 -160.6243519 124.5557174 96.62999518 -79.3662406	53.94623794 72.26687673 -14.00267745	-9.647640652 0.75050164 44.9709839	Cleaned dust from sensors Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	18.35 Cameron Turner
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2 2023-03-01 2022-07-30 1 2022-07-03 1	18:45:18 11:49:37 18:44:12 22:59:55 0:25:19 10:34:51 15:58:17	-76.82539022 -160.6243519 124.5557174 96.62999518 -79.3662406 -17.34307915	53.94623794 72.26687673 -14.00267745 19.39873467 -32.17974285	-9.647640652 0.75050164 44.9709839 -46.69161829	Cleaned dust from sensors Cleaned dust from sensors Replaced motor for joint 2 Adjusted joint velocity parameters	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	18.35 Cameron Turner 207.48 Billy Chavez 82.03 Lindsay Cruz
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2 2023-03-01 2022-07-30 1 2022-07-03 1 2024-05-22 2	18:45:18 11:49:37 18:44:12 22:59:55 0:25:19 10:34:51 15:58:17 22:46:38	-76.82539022 -160.6243519 124.5557174 96.62999518 -79.3662406 -17.34307915 -79.11380698	53.94623794 72.26687673 -14.00267745 19.39873467 -32.17974285 -6.428362746	-9.647640652 0.75050164 44.9709839 -46.69161829 32.91650886	Cleaned dust from sensors Cleaned dust from sensors Replaced motor for joint 2 Adjusted joint velocity parameters Routine check-up	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	18.35 Cameron Turner 207.48 Billy Chavez 82.03 Lindsay Cruz 78.37 Andre Barnes
2022-09-16 2023-03-01 1 2022-07-01 1 2024-03-22 1 2023-11-05 2 2023-03-01 2022-07-03 1 2022-07-03 1 2024-05-22 2 2022-07-26 1	18:45:18 11:49:37 18:44:12 22:59:55 0:25:19 10:34:51 15:58:17 22:46:38 10:02:06	-76.82539022 -160.6243519 124.5557174 96.62999518 -79.3662406 -17.34307915 -79.11380698 82.31772372	53.94623794 72.26687673 -14.00267745 19.39873467 -32.17974285 -6.428362746 99.7997011	-9.647640652 0.75050164 44.9709839 -46.69161829 32.91650886 -42.03470224	Cleaned dust from sensors Cleaned dust from sensors Replaced motor for joint 2 Adjusted joint velocity parameters	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	18.35 Cameron Turner 207.48 Billy Chavez 82.03 Lindsay Cruz

An in the color of the color						
					Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	62.57 Scott Gutierrez
	2022-10-15 6:49:00	-34.5975471	-20.62590873	41.92941953 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	232.24 Louis White
15.00 15.0	2023-04-20 0:55:38	-82.38295253	53.01535119	37.04931681 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	39.8 Bethany Arias
	2022-07-21 7:08:42	68.57867481	-3.791781037	16.05352909 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	9673.05 Mark Crawford
March 1988 1988 1988 1988 1988 1988 1989	2022-11-12 21:37:42	1.385824788	57.51386108	-15.88173685 Replaced damaged end effector		221.55 Clayton Sims
	2024-03-05 2:04:14	83 2895309	-75 34769306	-17 63504789 Cleaned dust from sensors		24 9 Matthew Williams
2007-2016-2016-2016-2016-2016-2016-2016-2016						
200 11 12 12 12 12 12 12						
March 1985						
1985 1985						
April 1997 1997 1998 1						
1.50 1.50						
Page					Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	51.9 Matthew Perry
1985 1986	2022-12-22 19:34:18	47.9488912	43.8412648	19.38558156 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	28.13 Brenda Hogan
20.00 10.0	2023-01-18 17:10:05	27.2298624	29.76504997	31.11571328 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	72.43 Heather Allison
	2023-11-15 0:31:09	-67.65987092	13.86614979	-19.97847659 Replaced motor for joint 2		425.92 Veronica Swanson
Page					Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	27.65 Melissa Cervantes
1906 1907	2022-09-29 6:01:51	3 023939887	66 4543637	32 08504235 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all channes in the system log and verified correct operation post-intervention.	16 98 Samantha Mcconnell
1985 1985	LULL OU OL L.LITO	40.E1 E00E04				OUT.OF FRIGION LONIO
1985 1985	2022-08-09 1:58:34	12.65311973	78.84452907	32.04586149 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	90.38 Allen Whitaker
	2023-07-08 15:59:45	123.1310222	19.69633714	-3.017768119 Tightened loose bolts on base		23.82 Sarah Ferguson
	2023-02-13 15:57:04	-62.44031529	-44.69252427	-23.29839054 Updated control software		148.66 Brittany Munoz
Section Sect						
292-14 Feb. 4 1179000 5 202-14						
200 1-19 1-20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						
202-0-1-19-22-22-2-2-2-2-2-2-2-2-2-2-2-2-2-2-				0.004727004 Olcarica data from scriboro		
2003-0-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-						
				-32.8684582 Replaced entire robotic arm (irreparable damage)		5376.35 Ronald Walton
200.04 201.05 1.0	2022-08-15 4:54:56	-173.8278365	66.8122209	-23.09864923 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	89.81 Dawn Haynes
1971-1967-1971-1971-1971-1971-1971-1971-	2022-12-19 22:03:15	169.9450274	-8.385449346	-49.48870033 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	51.62 Alexandra Hughes
	2023-06-11 19:25:37	15.89439955	-67.7244143	-30.09693287 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	55.99 James Santos
	2024-04-30 23:08:57	71.21354079	-91.27803882	20.47533125 Recalibrated torque settings	Intervention: Recalibrated torque settings, Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	140.75 Adam Jackson
2021-1-19 (2.17)						
1920 1913 19	2023-01-19 22:07:32	-153 7108759	-92 86478288	-36 15948935 Recalibrated torque settings	Intervention: Recalibrated formus settings. Performed a comprehensive check and recalibrated all parameters to ensure onlined performance. Documented all changes in the system for and verified correct operation post-intervention.	95.47 Melanie Wilson
2021-13 1 1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2						
2021-14 (1942) VI 1- (2025) VI						
2021-14-19 (2011) 40 (2011						
2021-1-10-1216 - 40-6455599 1-510-1216 1						
2021-1-10 1977-07 - 46. A MARKINET S. A MARK						252.61 Philip Adams
2020-04-03 (2.00 %) 7. 4,5000000000000000000000000000000000000						
Product of 23 (23 (23 (23 (23 (23 (23 (24 (23 (23 (23 (24 (23 (23 (23 (24 (23 (23 (23 (23 (23 (23 (23 (23 (23 (23	2023-11-30 8:37:47	-66.44996538	-41.67546674	-39.01393257 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	61.51 Robert Young
2023-14 S 2013-20 5 1-74 S 2014-20 5 1-7	2023-06-20 13:05:28	74.80982167	-36.57615183	-15.66809946 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	8526.93 Jon Fleming
2020.4-10.27 (20.77 4.1 (20.81 51.10 51.0 51.0 51.0 51.0 51.0 51.0 51	2024-03-24 2:53:28	47.45450226	20.83688637	15.796908 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	78.18 Richard Larson
2024-0-19 20-19 1-19 20-	2023-04-05 21:33:35	-174.3334644	55.42477402	-11.40049558 Replaced damaged end effector	Intervention: Replaced damaged end effector, Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	431.48 Scott Ruiz
2024-0-19 20-19 1-19 20-	2023-01-28 0:07:44	-139.6316146	-61.55917817	-34.82591104 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	61.22 Cassie White
19.03-45-19.32.05 19.03-26.05						230 95 Matthew Rodgers
2023-14 07-12 0-33 09570 9-48 255970 9-48						
2023-0-19 17-19 2-18 - 14 50-000 Programme of Contract Operation position in evention. Populate effects records arm (respeatable damage). Ferformed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system tog and verified correct operation position in evention. 2023-0-19 17-19 2-19 2-19 2-19 2-19 2-19 2-19 2-19 2						
2023-0-173-0-25 40-050-1737 6						
2021-10-20 (20 14-20 46 A40-40777 A 32 A40-40777 A 32 A40-40778 A						
2022-1-10-20-20-20-20-20-20-20-20-20-20-20-20-20						
2023-40-14 2005 19 40-82007 19 18 40-82007 19 18 18 18 19 19 19 18 18 19 19 19 19 18 18 19 19 19 19 18 19 18 19 19 19 19 19 19 18 19 19 19 19 19 19 19 19 19 19 19 19 19						
202-04-14 x 0.052						
2023-01-12 (2015)2 (1982-0237-03 1982-0237-03 1982-0237-03 1982-037-03 1982-037-03 1982-037-03 1982-037-03 1982-037-03 1982-037-03-037-03-037-03-037-03-037-03-03-037-03-03-03-03-03-03-03-03-03-03-03-03-03-						
2023-0-13 17,84-45802 7,73 18,445802 7,73 18,445802 7,73 18,445802 7,73 18,74540 10,73 18,74540			10.1000110			
2023-0-22 23 23 57 18 23 18 23 49.59 147.22 27 23 57 20 10 10 1990308 d 78 85 13 17 29 85 147.22 Paginace draws copyring and verified correct operation post-intervention. 2023-10-23 16 43.20 18 23 45.25 27 24 24 25 25 27 24 25 25 27 24 25 25 25 27 24 25 25 25 27 24 25 25 25 25 25 25 27 24 25 25 25 25 25 25 25 25 25 25 25 25 25	2022-09-14 22:09:52	169.8242377	3.45684844	-17.41399837 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6571.29 Anthony Williams
2023-10-29 16.43.00 1 00.9990389	2023-07-31 19:56:39	178.4450892	-71.31247943	0.676156944 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	47.88 Amy King
2023-10-29 16.43.00 1 00.9990389	2023-04-25 22:24:35	179.8318352	49.93914762	31.73266799 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation onst-intervention	173.88 Mark Blanchard
2023-10-29 163-301 83.5484575 7 48.5985222 7.905810742 Replaced entire robotic arm (irreparable damage) intervention. Replaced entire robotic arm (irreparable damage) intervention. Replaced entire robotic arm (irreparable damage) intervention. 2023-10-13 21-0355 2.9460371427 77 78091098 3 2.92748037 Replaced damaged end effector. Ferformed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 475.86 Jamin Recalibrated all parameters to ensure optimal performance. Documented all changes in the system log						
2022-10-13 21-03 24-03-03-13-03-03-03-03-03-03-03-03-03-03-03-03-03						
2022-09-29 137-52 7-342465227 88 98 4736283 5 19.98707108 Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 68.33 Sleven Costa 105-00-12 (19.00-12) (19.0						
2023-11-01 1024-13 225-2468 3 38203785 2 387674803 Rouline check-up intervention. Rouline check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 2024-01-25 10:06-88 4 -123-379155 225-25808 3 25202800 3 2-58764803 Rouline check-up puril intervention. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 2023-01-01 15:24-47 1-47-7475 5 46918141 1 1-47-7475 9 1-47-74715 9 1-47-74-7415 9 1-47-74715 9 1-47-74-74715 9 1-47-74715 9 1-47-74715 9 1-47-74715 9 1-47-74715 9 1-4						
2023-01-13 10-04-08 03 4719245 35 23228803 2-587742057 Replaced power supply unit Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 158.95 Carol Bell 11,8305-0210 12,000 12,						
2024-01-26 10.06.48 - 123.3750153 22.97947529 44.71819857 Adjusted joint velocity parameters intervention. Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 24.95 Cland Jones 14.7474767 24.7474767 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.7474776 24.74747776 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.747476 24.						
2023-07-19 15:2447 75.4981814						
2023-03-02 224-06 8, 10,2204748 8-placed motor for joint 2 Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 153.845 Bryan Miller 2023-03-01 185559 13,8773001 14,84502288 14,84502288 14,84502288 14,84502288 14,84502288 14,84502288 14,84502288 14,84502289 14,84502288 14,84502288 14,84502289 14,845022				, , , , , , , , , ,		
2023-03-02 22-240 B 10 22024 Fee Jan 10	2023-07-19 15:24:47	-14.7474176	75.49618141	-11.35092121 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	21.62 Gina Jones
2023-03-01 18-55.50 313.877305 54.3450288 24.1140064 Replaced power supply unit Intervention. Replaced power supply unit Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system tog and verified correct operation post-intervention. 153.66 Christiana Carroll Intervention. 2093-86 Jerminal National Performance on Pe	2023-03-20 22:24:06	-81.02204748	90.70360028	17.15557444 Replaced motor for joint 2		449.97 Julie Smith
2022-07-02 23-59-46 22 492984 59.1555288 23.82 Updated control software Intervention: Updated control software Up	2023-03-01 19:55:50	-131.8773061	-54.34502858	24.1164064 Replaced power supply unit		148.45 Bryan Miller
2023-08-04 5.35:18 148.1163228 13.59181748 29.48216181 Updated control software Intervention: Updated control software Updated con						
2023-12-15 12-37-34 - 2.6. 82300025 64.11331333 9.30935199 Ádjusted joint velocity parameters Intervention: Adjusted joint velocity parameters Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 146.931 Fixed Parameters 146.931 Fixed Paramet						
2023-02-27 0-28-27 - 168 8266279 - 9-307769735 - 49-11464315 Replaced power supply unit Intervention: Replaced power supply unit Intervention: Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 26.99 Jamin Wang 2022-14-01 81.007 - 18-00-						
2022-11-01 8.10.07 118.1084724 43.83298476 3.5 6132789 Cleaned dust from sensors Intervention Cleaned dust from sensors Intervention 26.59 January Light of Control Contro						
2022-12-01 0.38-57 49, 82495547 - 10.74528576						
2022-09-08 1000:009 25 20148083 - 9-524217935 - 43 28733493 Replaced motor for joint 2 Intervention: Replaced motor for joint 2 Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 473.62 Wyett Lopez 2023-01-01 1027-38 43.34162225 43.28733493 Replaced motor for joint 2 Intervention: Replaced motor for joint 2 Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and the performance in the system log and verified correct operation post-intervention. 37.376 (Girdy Haracotter) and verified corre						
2023-01-01 1027:38 - 63.34 16225 2 80.15880081 7.831226846 Replaced power supply unit. Intervention: 157.04 Cindy Hanson 2022-11-06 12:05:05 - 25.7446743 73.61310931 6.918933295 Tightened loose boilts on base Intervention: 157.04 Cindy Hanson 2022-11-06 12:05:05 - 25.7446743 73.61310931 6.918933295 Tightened loose boilts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. 157.04 Cindy Hanson 23.57 Kendra Roberts DVM						
2022-11-06 1205:05 - 25.7446743 73.61310931 6.916933295 Tightened loose boilts on base Intervention: Tightened loose boilts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.						
2022-11-06 1205.05 -25.7446743 73.61310931 6.918933295 Tightened loose bolts on base Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	2023-01-01 10:27:38	-63.34162252	80.15886081	7.831226846 Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	157.04 Cindy Hanson
000 0100 01700100 01700 01700 01700 01700 01700 01700 01700 01700 01700 01700 0	2022-11-06 12:05:05	-25.74467443	73.61310931	6.916933295 Tightened loose bolts on base		33.57 Kendra Roberts DVM
2024-04-09 19.47:03 -165.0356748 63.62749231 -41.83593841 Updated control software Intervention: Updated control software Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation gost-intervention. 292.74 Jennifer Owens	2024-04-09 19:47:03	-165.0356748	63.62749231	-41.83593841 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	292.74 Jennifer Owens

2024-04-15 0:55:19		53.6312915	11.70728909 Replaced damaged end effector 48.6246483 Updated control software	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Undested control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Undested control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	292.77 Jason Austin 272.03 Julia Brewer
2023-09-22 1:03:30				Intervention: Adjusted joint velocity narameters: Performed a comprehensive check and recalibrated all parameters to ensure onlineal performance. Documented all changes in the system tog and verified correct operation post-intervention	90 93 Lauren Smith
2024-01-07 2:42:14	-146 2013566		27 77112469 Cleaned dust from sensors	Intervention: Closure d dust from yearsors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	25.33 Steven Havs V
024-02-26 7:47:17		18 99344556		Intervention. Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system log and verified correct operation post-intervention.	305.45 Thomas Walsh
	36.80858661	-47 1674934	-32.64112545 Adjusted joint velocity parameters	Intervention. Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	146.45 William Thornto
				Intervention. Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to source optimal performance. Documented all changes in the system to and verified correct operation post-intervention.	409 33 Christopher Ale
			40.30617505 Updated control software	Intervention. Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system tog and verified correct operation obst-intervention.	200.49 Miguel Carter
				Intervention. Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6692.6 Jose Jenkins
023-06-18 11:25:03		40.24448815	45.36188376 Recalibrated torque settings	Intervention. Recalibrated forcus settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and vertical performance optimals and the system log and vertical performance optimals.	55.07 Jessica Thomp
				Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	205 4 Caleb Brooks
			-21.36117005 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	67.81 Douglas Smith
4-03-03 13:35:25				Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	115.32 Heather Schult
023-01-11 0:14:21	179.9581162	56.71589758	-42.08313513 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	27.08 Sean Love
				Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	12.22 Derrick Robins
023-02-09 9:35:20	32 16420146	-73 05551161		Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	115.34 Sean Mathews
				Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	150 55 Melanie Ortiz
022-10-09 7:14:50		35.18774448	-43.03135886 Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	155.19 Jason Scott
22-10-07 21:36:40	-71.93634185	-56.84168077	31.47031587 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	289.66 Brian Keith
23-10-01 4:04:57	89.06385548	-55.55503242	41.84828686 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	16.07 Susan King
				Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	25.45 Sarah Martinez
2-05-26 12:32:14	-12.5006634	-17.69247586	-7.441422184 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	14.75 Elizabeth Thorr
				Intervention: Replaced motor for ioint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system to and verified correct operation post-intervention.	407 68 Miguel Martin
22-07-09 20:56:47			-23.21503248 Cleaned dust from sensors	Intervention. Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	19.12 Joel Shaw
			-2 822111322 Recalibrated torque settings	Intervention. Recalibrated forces settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system tog and verified correct operation post-intervention. Intervention. Recalibrated forces operation as the system tog and verified correct operation operations.	115.94 Jeffery Brady
23-10-11 11:06:04		-69 78491856		intervention: Reclaimated to triple settings. Ferrormed a comprehensive check and reclaimated and parameters to any extension and arranges in the system log and verified correct operation post-intervention. Intervention Replaced entire robotics mm (reprehabled damage), Performed a comprehensive check and reclaimated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention Replaced entire robotics mm (reprehabled damage), Performed a comprehensive check and reclaimated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6129.77 Justin Bowers
			35.29099649 Cleaned dust from sensors	intervention. Replaced dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure upon a direct personal performance. Documented and changes in the system tog and verified correct operation post-intervention. Intervention, Colleged dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure upon obtains performance. Documented all changes in the system tog and verified correct operation post-intervention.	16.78 Tammy Kenned
24-03-23 19:15:27		17 29246892	-23.1085727 Replaced power supply unit	intervention. Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented air changes in the system log and verned correct operation post-intervention. Intervention. Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented air changes in the system log and verified correct operation post-intervention.	278.19 Brian Morales
24-03-23 19:15:27				intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system tog and verienc correct operation post-intervention. Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system tog and verience correct operation post-intervention.	280.75 Brian Cherry
023-08-17 3:23:47	-155.1296788 175.816653	-91.1380/568 -35.8057023	19.95874837 Tightened loose bolts on base	intervention: Replaced power supply unt. Performed a comprehensive check and recalibrated all parameters to ensure optimize performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention Tabhened loose both to have Performed a comprehensive check and recalibrated all parameters to ensure optimize performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention Tabhened loose both on base. Performed ac comprehensive check and recalibrated all parameters to ensure optimize performance. Documented all changes in the system log and verified correct operation post-intervention.	280.75 Brian Cherry 22 Joseph Grahan
23-08-05 7:09:53					22 Joseph Grahan 250.35 Theresa Miller
				Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	
023-03-02 9:14:08		98.79873598	-45.42331441 Adjusted joint velocity parameters 5.110708466 Recalibrated torque settings	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	112.19 Bradley Kelley
024-02-18 9:12:38		93.97759683	5.110708466 Recalibrated torque settings -27.9608832 Tightened loose bolts on base	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention Techniqued toose both on base. Performed a comprehensive check and recalibrated all parameters to be ensure optimal performance. Documented all changes in the system to gad an evirtied correct operation post-intervention.	140.08 Lawrence John 44.01 Kimberly Kenne
		-47 6025575			
23-07-24 22:54:07				Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	51.2 Kristina Campb
23-07-28 6:25:22			11.92808808 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	13.6 Max Alexander
24-01-15 2:03:28			-31.14732352 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	35.25 Robert Smith
24-04-16 15:08:26				Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	423.84 Brian Avila
				Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	344.54 Jennifer Hollan
			-37.17397315 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	128.33 Erin Bell
022-06-29 2:43:42		78.06625102		Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	7120.43 Samuel Johnson
23-01-12 11:13:42				Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	9834.66 Jack Gonzalez
023-07-26 6:18:42			-45.37683779 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	384.8 Vanessa Klein
023-12-29 4:37:15	100.0011012	0.40440000	23.96008861 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	11.56 Sara Gillespie
023-11-25 4:54:19		22.37539214	23.07727748 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	26.12 Adriana Holme:
			-16.70034962 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	16.01 Kimberly Taylor
024-02-06 7:06:24	-42.24672001	-82.27379907	-46.71357156 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	7068.87 Vanessa Park
			-8.004532542 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	273.21 Mary Moore
022-10-31 2:34:33	15.91407453	76.51842165	-16.7454855 Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	419.2 Timothy Nelson
023-08-21 1:03:49	139.441113	92.58760789	29.05522395 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	52.25 Raymond Nava
023-08-22 9:10:00	177.249391	54.88619323	33.00940597 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	205.83 Donald Garcia
24-04-16 12:04:39	110.9774606	-14.5805165	-43.55285414 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	49.16 Fred Zimmerma
23-09-01 22:45:18	-158.2309855	34.1456144	6.039810742 Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	163.48 Judy Meadows
023-12-16 5:46:08	15.75547603	-13.14753585	24.39283401 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	19.55 Ryan Palmer
23-12-12 11:05:09	42.87500924	-22.62119645	-12.94074068 Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	197.29 Angela English
24-04-28 14:08:53	20.05717155	-87.21497731	40.58517716 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	9488.08 Carlos Clark
023-04-10 7:13:03	69.05496993	80.27376057	10.00591318 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	484.99 Gregory Torres
2-09-21 10:32:06	-63.48842325	-16.11332239	46.95945206 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	67.75 Benjamin Pruitt
023-05-14 1:05:09	-150.8260269	-98.38929291	-18.22016523 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6082.86 Anthony Lozan
023-09-19 9:13:13	-68.8709007	-8.377095811	-10.30323484 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	31.72 Jennifer Freem
3-03-31 12:25:08	121.2465675	-87.33157809	-41.23360793 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	61.5 Nicole Taylor
22-07-30 6:56:32	-26.6935115	-29.32185641	-29.07133959 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	94.54 Audrey Smith
24-04-05 9:03:52	-123.5192222	-32.07638869	47.89098379 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	115.75 Brenda Thomps
				Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	114.83 Richard Lewis
2-07-28 22:07:43		42.74514885	7.877466139 Updated control software	Intervention. Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system top and verified correct operation post-intervention.	119.35 Kimberly Schm
				Intervention. Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system to and verified correct operation post-intervention.	7614.98 Jennifer Carlso
22-09-26 7:28:13			-14.16939843 Replaced motor for joint 2	intervention. Replaced motor for joint 2. Performance acomprehensive check and replacements to ensure upon to ensure upon performance. Documented all changes in the system log and venture upon post-intervention.	219.6 Kristen Schneid
123-06-05 4:13:22				Intervention. Repeated under the product arm (repeated) to damage. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system to grant vention post-mater reproduction.	5869.4 Ricardo Mills
3-03-18 11:24:36			12.319108 Adjusted joint velocity parameters	Intervention. Replaced on the color parameters, Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct persons post-intervention. Intervention, related to the color parameters, performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	108.45 Dennis Leach
			-0.6385496994 Replaced damaged end effector	intervention. Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal periorinance. Documented all changes in the system to g and verined correct operation (best-intervention.) Intervention. Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system to g and verined correct operation (best-intervention.)	286.12 Mark Mitchell
			-18.58563381 Updated control software	intervention: replaced carmage often error. Performed a comprehensive check and recalarizated an parameters to ensure opininal periodicial and ranges in the system log and verified correct correct operation post-intervention. Intervention: Undested control soften experience of comprehensive check and recalibrated all parameters to ensure opininal periodicial all changes in the system log and verified correct correct operation post-intervention. Intervention Undested control soften experience of comprehensive check and recalibrated all parameters to ensure opininal periodicial all changes in the system log and verified correct operation post-intervention.	292.34 Lawrence How
24-02-13 3:59:31 2-11-18 22:39:23				intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented air changes in the system log and vertiled correct operation post-intervention. Intervention Recalibrated all parameters for ensure optimal performance. Documented air changes in the system log and vertiled correct operation post-intervention. Intervention Recalibrated all parameters to ensure optimal performance. Documented air changes in the system log and vertiled correct operation post-intervention.	8289.2 Michael Floyd
	-83.60706341	79.18249065 98.20132027	-21.95896032 Replaced entire robotic arm (irreparable damage) -26.84092089 Replaced motor for joint 2	intervention: Replaced entire rocotic arm (reparable damage). Performed a comprehensive check and recalibrated ail parameters to ensure optimal performance. Documented ail changes in the system log and vented correct operation post-intervention. Intervention Replaced motif or foil part 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented ail changes in the system log and vented correct operation post-intervention. Intervention Replaced motif or foil parameters to ensure optimal performance. Documented ail changes in the system log and vented correct operation post-intervention.	435.89 Andrea Wilson
22-12-27 3:08:37 4-02-11 19:09:59			4.975676345 Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	370.54 Jessica Roach
				Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	8232.96 Teresa Green
122-12-26 0:11:34		98.46127624	3.657312416 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	126.77 Dr. Nicholas La
				Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	41.06 Lindsey Whitak
22-11-23 6:44:18				Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	357.04 Jessica William
22-10-07 3:23:30			-20.05861902 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	67.6 Julie Sanders
		-69.7178037		Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	8939.13 Patrick Foster
		72 07270524	24.38469642 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	58.11 Chad Rivas
022-09-18 2:53:28 22-11-07 13:17:09					
22-11-07 13:17:09			29.64978807 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	31.09 Paul Austin
2-11-07 13:17:09 4-04-25 12:07:33 22-12-17 2:35:28	-20.46461249 -5.42408366	78.40521929 -39.04943136		Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention. Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	31.09 Paul Austin 38.83 Ernest Clement 28.09 Reginald Rice

2023-11-23 8:19:10	148.0406094	-87.98197725	-42.42124166 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	16.42 Dawn Flynn
022-08-14 21:42:55	17.35016121	18.02506306	4.729147004 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	41.68 Todd Howard
023-09-19 23:02:04	34.02244618	-83.72114359	-3.205965517 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	8811.77 Philip Williams
023-12-28 14:24:48	111.6620587	30.4217641	-28.47615394 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	54.17 Whitney Williams
022-11-20 13:33:55	129.80579	-13.34574178	-29.92508392 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	11.32 Russell Cochran
2022-08-28 9:46:56	45.97696057	29.82816802	-25.75392765 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	73.64 Darren Sharp
023-09-11 19:04:39	20.80814722	61.33104612	-23.11871051 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6008.66 Ryan Clarke
022-11-03 19:45:55	-160.1120205	79.02445103	19.53817701 Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	239.47 Mark Turner
2024-04-27 4:17:52	150.8846927	28.54225044	28.66475726 Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	443.52 Rachael Lara
023-09-22 13:39:40	-131.5350653	-41.40061446	-8.883751927 Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	153.79 Jeffrey Horton
2024-04-02 0:16:56	172.8999279	-90.92793599	6.746355473 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	43.65 Paul Potter
2024-04-14 3:27:00	-101.693729	-5.481235553	0.7788683527 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	399.5 Linda Guerra
2022-06-02 5:23:05	-147.7124933	-75.24831032	-16.69885614 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	174.33 Jane Peters
022-11-10 16:31:21	11.8210234	-91.33908406	35.07905776 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	23.68 John Hopkins PhD
2023-04-10 5:00:38	-94.89620073	-22.29854359	37.68960813 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	83.97 Erin Moon
024-01-05 23:29:50	-60.02932833	56.42431855	11.71298618 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	88 Joshua White
024-01-30 10:22:23	100.4979262	-41.5981669	-42.7560008 Replaced damaged end effector	Intervention: Replaced damaged end effector. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	471.54 Jessica Wood
2023-01-23 2:59:49	-76.40597731	67.89938826	-11.76064314 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6353.4 Lindsey Acosta
022-08-18 18:38:25	-162.802632	60.80148168	3.140673756 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	53.34 Jordan Andrews
2023-04-27 4:02:32	-136.1192261	49.63625047	-42.51378917 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	9779.61 Samuel Turner
2022-09-22 1:01:03	179.5085576	-88.17135718	-24.25158951 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	112.66 Paul Lawson
2023-05-18 2:59:49	-166.5772004	-61.62243611	-26.7825108 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	231.34 Dennis Brown
023-03-04 20:13:06	151.6024453	-69.47121093	20.56706717 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	271.84 Martha Evans
2022-09-10 4:43:13	99.47039982	-79.26226839	-21.40824284 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	101.26 Aaron Moody
022-11-05 16:52:15	-70.54093286	6.560603317	6.934980076 Cleaned dust from sensors	Intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	29.63 Michael Smith
023-05-28 21:58:45	-154.7817185	-71.17069157	-22.09292755 Routine check-up	Intervention: Routine check-up. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	83.99 John Johnson
024-02-07 18:19:54	-163.3097414	-35.83554612	-18.55685281 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	145.4 Megan Gonzalez
2023-05-03 6:17:31	111.6369129	25.77255075	29.04508714 Updated control software	Intervention: Updated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	192.15 Jennifer Singh
2022-11-18 2:14:23	-86.03192383	-30.68011125	-2.666658498 Replaced power supply unit	Intervention: Replaced power supply unit. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	208.03 Jessica Palmer
2022-10-04 9:36:05	155.8632512	90.60581387	-36.60650576 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	222.9 Shannon Rogers
023-07-06 18:03:26	2.277687862	80.82708348	-41,22896043 Replaced entire robotic arm (irreparable damage)	Intervention: Replaced entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6171.21 Rebecca Hoffman
2022-12-11 8:21:48	-50.52145866	79.05045146	-1.10697861 Replaced motor for joint 2	Intervention: Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	319.62 Amber Cook
2024-02-01 5:59:45	55.40624504	-51.13557721	-9.685268672 Cleaned dust from sensors	intervention: Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	10.36 Jamie Henderson
022-09-29 10:57:10		-14.11088886	5.6780822 Recalibrated torque settings	Intervention: Recalibrated torque settings. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	111.84 Nicole Harris
023-09-02 21:02:49	179.0528205	-95.67331701	11.66099859 Tightened loose bolts on base	Intervention: Tightened loose bolts on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	35.57 Timothy Reves
2024-05-18 3:50:56	173.7505586	-88.60152582	19.93244815 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	147.45 John Scott
2023-06-28 1:35:49		-40 65462183	-0.425825945 Tightened loose bolts on base	Intervention: Tightened loose bolls on base. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	46 14 Gabrielle Pearson M
2023-12-28 8:34:15		87 74191887	46 21176728 Undated control software	Intervention: Uodated control software. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	184 83 Steve Suarez
023-10-06 19:20:55		-26.73715111	22.70241213 Cleaned dust from sensors	Intervention. Cleaned dust from sensors. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	25.23 Darren Sullivan
023-03-09 19:02:43		-72.7810858	13.90752743 Replaced motor for joint 2	Intervention. Replaced motor for joint 2. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system to and verified correct operation post-intervention.	472.61 Tara Daniels
2023-07-06 5:26:25		-60 26083448	10.76934773 Replaced inition for joint 2 10.76934773 Replaced entire robotic arm (irreparable damage)	Intervention. Perpadical entire robotic arm (irreparable damage). Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	6915.2 Paula Phelos
023-11-12 14:01:22		-26.1240131	-6.940433066 Updated control software	intervention. Updated control Southern, Performed a comprehensive check and reclaimated an parameters to ensure optimal performance. Documented an intervention is unable to the control of the control o	113.45 Courtney Coleman
024-01-15 10:43:44		-27.48835625	-21.16253528 Adjusted joint velocity parameters	Intervention: Adjusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all changes in the system log and verified correct operation post-intervention.	83.71 Thomas Hensley
2022-09-11 6:51:51		-7.993111792	44.768169 Routine check-up	Intervention. Routine check-tup. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system to and verified correct operation post-intervention.	73.71 Christopher Fitzpatri
2022-03-11 0:31:31		80.45607683	-22.97013966 Updated control software	intervention. Notice descript in contracting the contracting t	286.58 Kimberly Goodman
023-10-29 21:51:00		-40.14945374	12.91019317 Routine check-up	Intervention. Optated colours sources, retinined a comprehensive check and recalibrated all parameters to ensure uprimaring performance. Documented all changes in the system tog all not system tog and verified correct operation post-intervention. Intervention: Action the checkup reformed a comprehensive check and recalibrated all parameters to ensure optimal periorinance. Documented all changes in the system tog and verified correct operation post-intervention.	81.8 Robin Charles
2023-03-20 4:10:37	63 46669845	19 89954707	-12.00718171 Cleaned dust from sensors	Intervention. Roume unex-up. Ferrormed a comprehensive utex, and recamberage the analysis of the properties of the prope	11.58 Michael Patterson
		39.28129638	-24.77109127 Adjusted joint velocity parameters	Intervention. Cadious for intervention and intervention a	74.55 Michael Carlson
LULU 10-10 U. 12.2U	54.000m1 d23	28.51467202	7.4793435 Adjusted joint velocity parameters	Intervention. Augusted joint velocity parameters. Performed a comprehensive check and recalibrated all parameters to ensure optimal performance. Documented all chances in the system to gard vernice control person post-mere	137.73 Rvan Johnson