

HUSKY

QUALIFY FORM

Product Name	SFC12453					
Material Number	11136					
Material Description	RSN 574.189 LLD POLYETHLE					
Date Created	06/02/2017					

Tool Number	SFC12	
Resin/Aditive Number		
Resin/Aditive Descrip		
	Std.	Cert.

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :			
Final Part(s) Weight (g	155.220	156.0	156.780

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data	•					
Nozzle Tip %	1%	Mold Gate Temp °F		Fill Only Time	1.40	Machine Number: H301				
Nozzle Body %		Mold Fixed ½ °F		Fill Only Weight	146.0					
Adapter 1 (EX)	1%	Mold Moving ½ °F		Steel Temp. "A" Side °F	91					
S/H Heat (EX)		Stripper or other °F	60	Steel Temp. "B" Side °F	85					
Barrel Head (EX)		Nozzle Tip Informa	ation	Melt Temp. °F	390					
Barrel Front (EX7)		Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)		Length OAL (in.)	0.00	Open						
Barrel Center (EX5)		Orifice Size (in.)	0.00	Close						
Barrel Center (EX4)	400	Nozzle Body Information		PSI						
Barrel Center (EX3)	400	Length OAL (in.)	0.00	Delay						
Barrel Center (EX2)	395									
Barrel Rear (EX1)	390									
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	C3	C4		
Shot size in.	80.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	40	Pre-Pullback Stroke m		Hold (Sec)						
Injection Velocity mm/s	35	Screw Start Delay		Exhaust (Sec)						
Injection Velocity mm/s	30	Screw Chg Position		Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	70	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM		Pessure 2 (PSI)						
Injection Change Pos 1	28.0	Back Pressure 1	20.0	Time (Sec)						
Injection Change Pos 2	20.0	Back Pressure 2	20.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s	99.00	Position 1 Gate/HB/Man						
Injection Change Pos 4		Post Pullback Stroke	9.00	Position 2 Gate/HB/Man						
Trans Pos. mm		Screw positon after SB	89.00	Position 3 Gate/HB/Man						
Injection Press Limit	810	Screw recovery time	9.34	Position 4 Gate/HB/Man						
Inj PSI at transfer	790	Cooling time secs		Position 5 Gate/HB/Man						
Injection time act. secs.	1.43	Mold protect press		Position 6 Gate/HB/Man						
Hold Press 1 PSI	325	Mold protect time		Start-Up Instructions / Comments						
Hold Press 2 PSI	275	Clamp tonnage	250			3				

Source: Machine Run Database

Hold Press 1 secs

Hold Press 2 secs

Final Cushion mm

Injection pressure gauge

Back pressure gauge psi
Back pressure gauge psi

1.00 Holding 1 gauge psi

7.2 Holding 2 gauge psi

2.00