

Version No.

## **QUALIFY FORM**

**HUSKY** 

Product Name	RFS2SCPP190
Material Number	11160
Material Description	RSN R12C-01 CLARFD PP
Date Created	10/23/2018

Tool Number	RFS2SEALCOVER				
Resin/Aditive Number					
Resin/Aditive Descrip					
	Std.	Cert.			

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.	
Certifield Cycle Time :				
Final Part(s) Weight (g	52.740	53.0	53.270	

## ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data						
Nozzle Tip %		Mold Gate Temp °F	72	Fill Only Time	2.00	Machine Number: <b>H301</b>				
Nozzle Body %	10	Mold Fixed ½ °F	120	Fill Only Weight	46.7					
Adapter 1 (EX)	10	Mold Moving ½ °F	140	Steel Temp. "A" Side °F	80					
S/H Heat (EX)		Stripper or other °F		Steel Temp. "B" Side °F	100					
Barrel Head (EX)		Nozzle Tip Informa	ation	Melt Temp. °F	385					
Barrel Front (EX7)		Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)		Length OAL (in.)	0.00	Open						
Barrel Center (EX5)		Orifice Size (in.)	0.00	Close						
Barrel Center (EX4)	380	Nozzle Body Information		PSI						
Barrel Center (EX3)	400	Length OAL (in.)	0.00	Delay						
Barrel Center (EX2)	400			·						
Barrel Rear (EX1)	400									
Injection Profile	Set	Recovery & Clamp	Profile	Gas Assist	C1	C2	СЗ	C4		
Shot size in.	50.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	30	Pre-Pullback Stroke m		Hold (Sec)						
Injection Velocity mm/s	30	Screw Start Delay		Exhaust (Sec)						
Injection Velocity mm/s		Screw Chg Position		Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	160	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM		Pessure 2 (PSI)						
Injection Change Pos 1	48.0	Back Pressure 1	140.0	Time (Sec)						
Injection Change Pos 2	35.0	Back Pressure 2	140.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s	100.00	Position 1 Gate/HB/Man	480					
Injection Change Pos 4		Post Pullback Stroke	20.00	Position 2 Gate/HB/Man						
Trans Pos. mm		Screw positon after SB	71.00	Position 3 Gate/HB/Man						
Injection Press Limit	2000	Screw recovery time	2.50	Position 4 Gate/HB/Man						
Inj PSI at transfer	1351	Cooling time secs		Position 5 Gate/HB/Man						
Injection time act. secs.	10.00	Mold protect press	200	Position 6 Gate/HB/Man						
Hold Press 1 PSI	560	Mold protect time		Start-Up Instructions / Comments						
Hold Press 2 PSI	450	Clamp tonnage	300							
Hold Press 1 secs	3.00	Injection pressure gauge	1396	1						
Hold Press 2 secs	3.00	Holding 1 gauge psi	560	1						
Final Cushion mm	24.0	Holding 2 gauge psi	450	1						
		Back pressure gauge psi		1						
		Back pressure gauge psi		1						
				1						

Page 1 of 1 8:36:08AM

Validated by: