HAITIAN

Run Sheet - CONFIDENTIAL

VALIDATING FORM

Product Name	HT8CW135		
Material Number	11100		
Material Description	RSN CLR MKRN 2856-550042/		
Date Created	09/19/2018		

Tool Number	80ZHBTUM	8OZHBTUMBLER		
Resin/Aditive Number				
Resin/Aditive Descrip				
	Std.	Cert.		

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	24.50	26.0	26.00
Final Part(s) Weight (gm)	235.320	236.5	237.680

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS **Barrel Temperatures** Set **Mold Cooling Temps** Set Reference Data Nozzle Tip % 20 Fill Only Time **HT49** Machine Number: Mold Gate Temp °F 135 5.00 Nozzle Body % 20 165 Fill Only Weight 232.9 Mold Fixed ½ °F 500 Adapter 1 155 Steel Temp. "A" Side °F Mold Moving 1/2 °F 171 Barrel Front (HT2) 580 163 Stripper or other °F Steel Temp. "B" Side °F Barrel Center (HT3) **Nozzle Tip Information** 580 580 Melt Temp. °F Barrel Center (HT4) 580 Type GP, FT, NYL Valve Gate VG1 VG2 VG3 VG4 Tm/Pos Barrel Center (HT5) 0.00 Open Tm/Pos Tm/Pos Tm/Pos 570 Length OAL (in.) Time 0.00 Barrel Center (HT6) Orifice Size (in.) Pos Barrel Center (HT7) **Nozzle Body Information** Tm/Pos Tm/Pos Close Barrel Rear (HT8) Tm/Pos Tm/Pos Length OAL (in.) Time Pos On/Off Hold On/Off On/Off Injection Profile Set **Recovery & Clamp Profile** On/Off Delay Shot size in. 3.30 0.10 Suckback Before Pos Injection Change Pos 1 Active 2.90 Screw Start Delay Injection Change Pos 2 1.00 Box 1 Box 2 Box 3 Box 4 Box 5 Box 6 Hot Tip Controller Charge Position 1 Injection Change Pos 3 Position 1 Gate/HB/Man 655 Charge Position 2 Injection Change Pos 4 Charge Pressure 1 700 Position 2 Gate/HB/Man 655 Injection Press 1 Charge Pressure 2 600 700 Position 3 Gate/HB/Man 656 Injection Press 2 1600 40 Position 4 Gate/HB/Man 645 Charge Flow 1

Position 5 Gate/HB/Man

Position 6 Gate/HB/Man

Injection Press 3 Charge Flow 2 40 Injection Press 4 250.0 Back Pressure 1 Injection Press 5 Back Pressure 2 200.0 Injection Flow 1 0.10 8 Suckback After Pos Injection Flow 2 46 Screw Positon After SB 3.50 Injection Flow 3 Screw charge Time 10.0 Injection Flow 4 11.0 Cooling time secs Injection Flow 5 300 Mold protect press Inj Position threshold 1.00 99 Mold Protect Flow Inj Pressure threshold Mold protect time InjectionTime threshold Clamp High Press PSI 1950 Inj PSI at transfer Clamp High Press Flow 60 Injection time act. secs. 1700 5.00 Injection pressure gauge Hold Press 1 PSI 500 500 Holding 1 gauge psi Hold Press 2 PSI 450 Holding 2 gauge psi Hold Flow 1 40 Back pressure gauge psi Hold Flow 2 Back pressure gauge psi Hold Time 1 2.00 Hold Time 2 2.00

1.00

Final Cushion mm

Start-Up Instructions / Comments

610

610