

Hold Press 2 secs

Final Cushion mm

Holding 1 gauge psi

Back pressure gauge psi

Back pressure gauge psi

3.6 Holding 2 gauge psi

Version No.

CERTIFIED FORM

HUSKY

Product Name	PR314151
Material Number	11252
Material Description	RSN PFSG722 PP COPOLYME
Date Created	08/22/2017

Tool Number	PR314	
Resin/Aditive Number		
Resin/Aditive Descrip		
	Std.	Cert.

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	2.00

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	63.00	64.5	64.50
Final Part(s) Weight (g	1836.770	1846.0	1855.230

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

ALL DATA	BELOW IS F	REFERENCE ONLY AND SE	TTINGS CAI	N BE ADJUSTED IF REQUIR	RED IN ORDE	R TO MEE	T PRODUC	T STANDAI	RDS	
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data		Machine Number: H603				
Nozzle Tip %	40	Mold Gate Temp °F	100	Fill Only Time	10.20					
Nozzle Body %		Mold Fixed ½ °F	100	Fill Only Weight	1788.0					
Adapter 1 (EX)	420	Mold Moving ½ °F	65	Steel Temp. "A" Side °F	125					
S/H Heat (EX)	450	Stripper or other °F		Steel Temp. "B" Side °F	116					
Barrel Head (EX)	450	Nozzle Tip Informa	ation	Melt Temp. °F	461					
Barrel Front (EX7)		Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)	450	Length OAL (in.)	0.00	Open						
Barrel Center (EX5)	450	Orifice Size (in.)	0.00	Close						
Barrel Center (EX4)	450	Nozzle Body Inform	nation	PSI						
Barrel Center (EX3)	375	Length OAL (in.)	0.00	Delay						
Barrel Center (EX2)	370									
Barrel Rear (EX1)	370									
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	C3	C4		
Shot size in.	308.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	25	Pre-Pullback Stroke m		Hold (Sec)						
Injection Velocity mm/s	35	Screw Start Delay		Exhaust (Sec)						
Injection Velocity mm/s	15	Screw Chg Position	140.0	Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	140	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM	140	Pessure 2 (PSI)						
Injection Change Pos 1	285.0	Back Pressure 1	155.0	Time (Sec)						
Injection Change Pos 2	35.0	Back Pressure 2	155.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s		Position 1 Gate/HB/Man	450	450				
Injection Change Pos 4		Post Pullback Stroke	15.00	Position 2 Gate/HB/Man	450					
Trans Pos. mm	15.00	Screw positon after SB	323.10	Position 3 Gate/HB/Man	450					
Injection Press Limit	1600	Screw recovery time	25.80	Position 4 Gate/HB/Man	450					
Inj PSI at transfer	902	Cooling time secs	35.0	Position 5 Gate/HB/Man	450					
Injection time act. secs.	10.20	Mold protect press	650	Position 6 Gate/HB/Man	450					
Hold Press 1 PSI	600	Mold protect time		Start-Up Instruct	ions / Comi	nents				
Hold Press 2 PSI		Clamp tonnage	350							
Hold Press 1 secs	7.00	Injection pressure gauge	997							
				•						

603

158

158

Page 1 of 1 9:56:25AM

Validated by: