## **HAITIAN**

#### Run Sheet - CONFIDENTIAL

### **VALIDATING FORM**

Product Name	30CWCH135
Material Number	11100
Material Description	CLEAR POLYCARB
Date Created	09/27/2018

Tool Number	GN30HCOVER#2		
Resin/Aditive Number			
Resin/Aditive Descrip			
	Std.	Cert.	

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :			
Final Part(s) Weight (gm)	380.090	382.0	383.910

### ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

ALE BAIA	D	CEI EILENGE GILEI AND GE		TE ABOUTED II REQU
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data
Nozzle Tip %	2	Mold Gate Temp °F	10	Fill Only Time
Nozzle Body %	2	Mold Fixed ½ °F	180	Fill Only Weight
Adapter 1 (HT1)	495	Mold Moving ½ °F	165	Steel Temp. "A" Side °F
Barrel Front (HT2)	600	Stripper or other °F		Steel Temp. "B" Side °F
Barrel Center (HT3)	600	Nozzle Tip Informa	ation	Melt Temp. °F
Barrel Center (HT4)	600	Type GP, FT, NYL	gp	Valve Gate
Barrel Center (HT5)	580	Length OAL (in.)	2 3/4	Open
Barrel Center (HT6)		Orifice Size (in.)	7/32	Time
Barrel Center (HT7)		Nozzle Body Inform	nation	Pos
Barrel Rear (HT8)		Length OAL (in.)	6.0	Close
				Time
				Pos
Injection Profile	Set	Recovery & Clamp I	Profile	Hold
Shot size in.	3.80	Suckback Before Pos		Delay
Injection Change Pos 1	3.65	Screw Start Delay		Active
Injection Change Pos 2	2.00	Charge Position 1	0.50	Hot Tip Controller
Injection Change Pos 3	1.40	Charge Position 2		Position 1 Gate/HB/Man
Injection Change Pos 4		Charge Pressure 1	950	Position 2 Gate/HB/Man
Injection Press 1	600	Charge Pressure 2		Position 3 Gate/HB/Man
Injection Press 2	1500	Charge Flow 1	65	Position 4 Gate/HB/Man
Injection Press 3	1555	Charge Flow 2	65	Position 5 Gate/HB/Man
Injection Press 4	1755	Back Pressure 1	175.0	Position 6 Gate/HB/Man
Injection Press 5		Back Pressure 2	150.0	Start-Up Instruc
Injection Flow 1	10	Suckback After Pos	0.10	
Injection Flow 2	32	Screw Positon After SB	3.99	
Injection Flow 3	32	Screw charge Time	14.0	
Injection Flow 4	30	Cooling time secs	15.5	
Injection Flow 5		Mold protect press	700	
Inj Position threshold	0.60	Mold Protect Flow	75	
Inj Pressure threshold		Mold protect time		
InjectionTime threshold		Clamp High Press PSI	1900	†
Inj PSI at transfer		Clamp High Press Flow	29	•
Injection time act. secs.	4.70	Injection pressure gauge	1600	•
Hold Press 1 PSI	450	Holding 1 gauge psi	750	•
Hold Press 2 PSI	550	Holding 2 gauge psi	650	•
Hold Flow 1	45	Back pressure gauge psi		•
Hold Flow 2	45	Back pressure gauge psi		•
Hold Time 1	3.00			
Hold Time 2	2.00			
l		<del> </del>		†

0.00

Final Cushion mm

Machine Number: **HT45** 

VG3

Tm/Pos

Tm/Pos

On/Off

Box 3

VG4

Tm/Pos

Tm/Pos

On/Off

Box 4

Box 5

Box 6

4.70

377.0

184 169

592

VG2

Tm/Pos

Tm/Pos

On/Off

Box 2

VG1

Tm/Pos

Tm/Pos

On/Off

Box 1

550

510

550

550 550

# Start-Up Instructions / Comments