

Version No.

HAITIAN VALIDATING FORM

Product Name	21157CBP180
Material Number	11187
Material Description	RSN 6719 HDPE (INJ/MTC)
Date Created	09/08/2017

Tool Number	21157CB#2				
Resin/Aditive Number					
Resin/Aditive Descrip					
	Std.	Cert.			

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	1.50

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	53.00	54.5	54.50
Final Part(s) Weight (gm)	1684.540	1693.0	1701.470

Final Part(s) Weight (gm)	1684.540	1693.0 1701.470								
ALL DATA	BELOW IS F	REFERENCE ONLY AND SE	TTINGS CAI	N BE ADJUSTED IF REQUIR	RED IN ORDI	ER TO MEE	T PRODUC	T STANDA	RDS	
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data		Machine Number: HT1502				
Nozzle Tip %		Mold Gate Temp °F	75	Fill Only Time	5.00					
Nozzle Body %		Mold Fixed ½ °F	65	Fill Only Weight	1635.0					
Adapter 1 (HT1)	460	Mold Moving ½ °F	65	Steel Temp. "A" Side °F	104					
Barrel Front (HT2)	515	Stripper or other °F		Steel Temp. "B" Side °F	109					
Barrel Center (HT3)	520	Nozzle Tip Informa	ation	Melt Temp. °F	479					
Barrel Center (HT4)	520	Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (HT5)	515	Length OAL (in.)	0.00	Open	Tm/Pos	Tm/Pos	Tm/Pos	Tm/Pos		
Barrel Center (HT6)	510	Orifice Size (in.)	0.00	Time						
Barrel Center (HT7)	500	Nozzle Body Inform	nation	Pos						
Barrel Rear (HT8)	475	Length OAL (in.)	0.00	Close	Tm/Pos	Tm/Pos	Tm/Pos	Tm/Pos		
				Time						
				Pos						
Injection Profile	Set	Recovery & Clamp	Profile	Hold	On/Off	On/Off	On/Off	On/Off		
Shot size in.	7.40	Suckback Before Pos	0.50	Delay						
Injection Change Pos 1	0.90	Screw Start Delay	0.50	Active						
Injection Change Pos 2		Charge Position 1		Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Charge Position 2		Position 1 Gate/HB/Man	400					
Injection Change Pos 4		Charge Pressure 1	1500	Position 2 Gate/HB/Man	400					
Injection Press 1	1950	Charge Pressure 2		Position 3 Gate/HB/Man	450					
Injection Press 2	1400	Charge Flow 1	99	Position 4 Gate/HB/Man	450					
Injection Press 3		Charge Flow 2		Position 5 Gate/HB/Man	450					
Introtion Duran 4										

Injection Press 4 100.0 Position 6 Gate/HB/Man Back Pressure 1 Injection Press 5 Back Pressure 2 100.0 Injection Flow 1 1.10 Suckback After Pos 50 Injection Flow 2 13 Screw Positon After SB 8.69 Injection Flow 3 Screw charge Time Injection Flow 4 20.0 Cooling time secs Injection Flow 5 350 Mold protect press Inj Position threshold 40 Mold Protect Flow Inj Pressure threshold 0.55 Mold protect time InjectionTime threshold Clamp High Press PSI 2000 Inj PSI at transfer 35 Clamp High Press Flow 1169 Injection time act. secs. 1726 5.00 Injection pressure gauge Hold Press 1 PSI 600 592 Holding 1 gauge psi Hold Press 2 PSI 592 600 Holding 2 gauge psi Hold Flow 1 25 Back pressure gauge psi 145 Hold Flow 2 25 Back pressure gauge psi Hold Time 1 1.00 Hold Time 2 10.00

11.00

Final Cushion mm

Start-Up Instructions / Comments

Validated by:

Page 1 of 1 11:49:49AM