HAITIAN

Run Sheet - CONFIDENTIAL

VALIDATING FORM

Product Name	182612CW135
Material Number	11100
Material Description	RSN CLR MKRN 2856-550042/
Date Created	05/29/2018

Tool Number	182612CB	182612CB		
Resin/Aditive Number				
Resin/Aditive Descrip				
	Std.	Cert.		

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	69.50	71.0	71.00
Final Part(s) Weight (gm)	3467.580	3485.0	3502.430

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS **Barrel Temperatures** Set **Mold Cooling Temps** Set Reference Data Nozzle Tip % 120 Fill Only Time HT1504 7.80 Machine Number: Mold Gate Temp °F Nozzle Body % 120 185 Fill Only Weight 3450.0 Mold Fixed ½ °F Adapter 1 180 Steel Temp. "A" Side °F Mold Moving 1/2 °F 172 Barrel Front (HT2) 580 168 Stripper or other °F Steel Temp. "B" Side °F Barrel Center (HT3) **Nozzle Tip Information** 595 630 Melt Temp. °F Barrel Center (HT4) 655 Type GP, FT, NYL Valve Gate VG1 VG2 VG3 VG4 Barrel Center (HT5) 3 3/4 Open Tm/Pos Tm/Pos Tm/Pos Tm/Pos 655 Length OAL (in.) 1/4 Time Barrel Center (HT6) 655 Orifice Size (in.) Pos Barrel Center (HT7) **Nozzle Body Information** 655 Tm/Pos Tm/Pos Close Barrel Rear (HT8) 640 Tm/Pos Tm/Pos Length OAL (in.) Time Pos On/Off Hold On/Off On/Off Injection Profile Set **Recovery & Clamp Profile** On/Off Delay Shot size in. 10.15 Suckback Before Pos Injection Change Pos 1 Active 10.00 Screw Start Delay Injection Change Pos 2 20.00 9.00 Box 1 Box 2 Box 3 Box 4 Box 5 Box 6 Hot Tip Controller Charge Position 1 Injection Change Pos 3 Position 1 Gate/HB/Man Charge Position 2 Injection Change Pos 4 Charge Pressure 1 1600 Position 2 Gate/HB/Man Injection Press 1 2000 Charge Pressure 2 1600 Position 3 Gate/HB/Man Injection Press 2 2530 70 Position 4 Gate/HB/Man Charge Flow 1 **Injection Press 3** 2050 Charge Flow 2 60 Position 5 Gate/HB/Man

Injection Press 4 150.0 Back Pressure 1 Injection Press 5 Back Pressure 2 50.0 Injection Flow 1 0.60 Suckback After Pos 30 Injection Flow 2 46 Screw Positon After SB 10.15 Injection Flow 3 16 Screw charge Time 22.3 Injection Flow 4 35.0 Cooling time secs Injection Flow 5 700 Mold protect press Inj Position threshold 0.90 15 Mold Protect Flow Inj Pressure threshold Mold protect time InjectionTime threshold Clamp High Press PSI 2500 Inj PSI at transfer Clamp High Press Flow 20 16.80 Injection time act. secs. Injection pressure gauge Hold Press 1 PSI 500 Holding 1 gauge psi Hold Press 2 PSI 400 Holding 2 gauge psi

35

5.00

4.00

0.00

Back pressure gauge psi

Back pressure gauge psi

Hold Flow 1

Hold Flow 2

Hold Time 1

Hold Time 2

Final Cushion mm

Start-Up Instructions / Comments

Position 6 Gate/HB/Man