

Version No.

VALIDATING FORM

JSW

Product Name	UPCHHPCULTRASON
Material Number	11125A
Material Description	RSN ULTRASN NATURAL E30
Date Created	04/09/2019

Standardization Info	Min.	Mid.	Max.	
Certifield Cycle Time :	31.00	32.5	32.50	
Final Part(s) Weight (g	338.800	340.5	342.200	

Tool Number	SMLHTENCLOSURE2					
Resin/Aditive Number						
Resin/Aditive Descrip						
	Std.	Cert.				

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Final Part(s) Weight (g	338.800	340.5	342.200								
ALL DATA	BELOW IS R	EFERENCE	ONLY AND SE	TTINGS CAN	BE ADJUSTED IF REQUIR	ED IN ORDE	R TO MEET	PRODUCT	STANDAR	DS	
Barrel Temperatures	Set	Mold Cooling Temps		Set	Reference Data	Set					
Nozzle Tip %	50	Mold Gate Temp °F		200	Fill Only Time	3.02	Machine Number: 48				
Nozzle Body %	100	Mold Fixed ½ °F		300	Fill Only Weight	332.0					
Adapter (NH)	650	Mold Moving ½ °F		300	Steel Temp. "A" Side °F	295					
Barrel Front (H4)	710	Stripper or other °F			Steel Temp. "B" Side °F	288					
Barrel Center (H3)	710	Noz	Nozzle Tip Informat		Melt Temp. °F	710					
Barrel Center (H2)	710	Type GP, F	FT, NYL	GP	Valve Gate	VG1	VG2 VG3 VG4				
Barrel Rear (H1)	690	Length OA	L (in.)	3	Open Delay						
		Orifice Size	e (in.)	3/16	Open Time						
		Nozz	le Body Infor	mation	Adv Cls Tm						
		Length OA	L (in.)	6	Close Delay						
Injection Profile	Set	Recov	very & Clamp	Profile	Close Time						
Shot size in.	3.80	PrePullbk	(PB2)speed		Inj HP End						
Injection Press 1	95.00	PrePullbo	k before stro		Transfer						
Injection Press 2	95.00	Screw Star	rt Delay		Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Press 3		Screw Chg	Position 1		Position 1 Gate/HB/Man						
Injection Press 4		Screw Chg	Position 2		Position 2 Gate/HB/Man						
Injection Press 5		Screw reco	overy % 1	60.00	Position 3 Gate/HB/Man						
Injection Velocity 1	45.00	Screw reco	overy % 2		Position 4 Gate/HB/Man						
Injection Velocity 2	65.00	Back Press	sure 1	55.00	Position 5 Gate/HB/Man						
Injection Velocity 3		Back Press	sure 2		Position 6 Gate/HB/Man						
Injection Velocity 4		PostPullba	ick(PB1)speed	40.00	Start-Up Instructi	Start-Up Instructions / Comments					
Injection Velocity 5		Post Pullba	ack stroke in.	0.23							
Injection Change Pos 1	2.80	Screw pos	iton after SB	4.05							
Injection Change Pos 2		Screw reco	overy time	10.72							
Injection Change Pos 3		Cooling tim	ne secs	12.00							
Injection Change Pos 4		Mold prote	ct press	95.00							
Trans mode lvsh/lps	IVSH	Mold prote	ct time	5.00	1						
Trans pos in.	0.14	Clamp toni	nage	320							
lps PSI	2100	Injection pr	ressure gauge	2100							
Inj PSI at transfer	2100	Holding 1 g	gauge psi	500							
Injection time act. secs.	3.02	Holding 2 g	gauge psi								
Hold Press 1 %	50	Back press	sure gauge psi	300							
Hold Press 2 %		Back press	sure gauge psi								
Hold Time 1		Final Cush	ion	0.12							
Hold Time 2											
Injection Hold Time	12.00				Validated by:						
					7						

Page 1 of 1 12:01:25PM