

## Version No.

## **CERTIFIED FORM**

**HUSKY** 

Product Name	25E2151				
Material Number	11252				
Material Description	RSN PFSG722 PP COPOLYME				
Date Created	09/19/2017				

Tool Number	25E2	
Resin/Aditive Number		
Resin/Aditive Descrip		
	Std.	Cert.

Colorant Number	20519A
Colorant Descrip	CLR CC00015250WE SFT (
Color Percentage	2.00
MacGuire Setting	2.00

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	47.50	49.0	49.00
Final Part(s) Weight (g	772.120	776.0	779.880

## ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data							
Nozzle Tip %		Mold Gate Temp °F		Fill Only Time	5.90	Machine Number: <b>H604</b>					
Nozzle Body %		Mold Fixed ½ °F	90	Fill Only Weight	766.0						
Adapter 1 (EX)	450	Mold Moving ½ °F	65	Steel Temp. "A" Side °F	98						
S/H Heat (EX)	480	Stripper or other °F		Steel Temp. "B" Side °F	100						
Barrel Head (EX)	500	Nozzle Tip Informa	ation	Melt Temp. °F	489						
Barrel Front (EX7)		Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4			
Barrel Center (EX6)	460	Length OAL (in.)	0.00	Open							
Barrel Center (EX5)	460	Orifice Size (in.)	0.00	Close							
Barrel Center (EX4)	460	Nozzle Body Information		PSI							
Barrel Center (EX3)	460	Length OAL (in.)	0.00	Delay							
Barrel Center (EX2)	420			•							
Barrel Rear (EX1)	410										
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	C3	C4			
Shot size in.	133.0	Pre-Pullback mm/s		Delay (Sec)							
Injection Velocity mm/s	25	Pre-Pullback Stroke m		Hold (Sec)							
Injection Velocity mm/s	32	Screw Start Delay		Exhaust (Sec)							
Injection Velocity mm/s	10	Screw Chg Position	50.0	Pressure 1 (PSI)							
Injection Velocity mm/s		Screw Recovery RPM	85	Time (Sec)							
Injection Velocity mm/s		Screw Recovery RPM	85	Pessure 2 (PSI)							
Injection Change Pos 1	130.0	Back Pressure 1	150.0	Time (Sec)							
Injection Change Pos 2	35.0	Back Pressure 2	150.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6	
Injection Change Pos 3		Post Pullback mm/s		Position 1 Gate/HB/Man	380	450					
Injection Change Pos 4		Post Pullback Stroke	20.00	Position 2 Gate/HB/Man	380						
Trans Pos. mm	12.00	Screw positon after SB	153.00	Position 3 Gate/HB/Man	380						
Injection Press Limit	1000	Screw recovery time	18.15	Position 4 Gate/HB/Man	380						
Inj PSI at transfer	619	Cooling time secs	26.0	Position 5 Gate/HB/Man	450						
Injection time act. secs.	5.93	Mold protect press	500	Position 6 Gate/HB/Man	450						
Hold Press 1 PSI	500	Mold protect time		Start-Up Instructi	ions / Com	ments					
Hold Press 2 PSI		Clamp tonnage	500								
Hold Press 1 secs	7.00	Injection pressure gauge	674								
Hold Press 2 secs		Holding 1 gauge psi	499								
Final Cushion mm	5.4	Holding 2 gauge psi									
		Back pressure gauge psi	150								
		Back pressure gauge psi	149								
				†							
				Validated by:							

Page 1 of 1 1:09:17PM