

VALIDATING FORM

Product Name	32HPTBH1150
Material Number	11125A
Material Description	RSN ULTRASN NATURAL E30
Date Created	05/22/2019

l						
Standardization Info	Min.	Mid.	Max.			
Certifield Cycle Time :	32.50	34.0	34.00			
Final Part(s) Weight (g	266.660	268.0	269.340			

Tool Number	32НРТВН			
Resin/Aditive Number				
Resin/Aditive Descrip				
	Std.	Cert.		

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Box 6

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

ALL DATA	BELOW IS R	EFERENCE ONLY AND SET	TINGS CAN	BE ADJUSTED IF REQUIR	ED IN ORDE	R TO MEET	PRODUCT	STANDAR	DS	
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data	Set	Machine Number: 47				
Nozzle Tip %	100	Mold Gate Temp °F	200	Fill Only Time	3.29				1	
Nozzle Body %	100	Mold Fixed ½ °F	330	Fill Only Weight	262.5					
Adapter (NH)	600	Mold Moving ½ °F	225	Steel Temp. "A" Side °F	316					
Barrel Front (H4)	690	Stripper or other °F	225	Steel Temp. "B" Side °F	268					
Barrel Center (H3)	690	Nozzle Tip Informa	ation	Melt Temp. °F	739					
Barrel Center (H2)	690	Type GP, FT, NYL	GP	Valve Gate	VG1	VG2	VG3	VG4	İ	
Barrel Rear (H1)	680	Length OAL (in.)	2	Open Delay						
		Orifice Size (in.)	1/8	Open Time						
		Nozzle Body Information		Adv Cls Tm						
	Length OAL (in.) 6		6	Close Delay						
Injection Profile	Set	Recovery & Clamp I	Profile	Close Time						
Shot size in.	3.00	PrePullbk(PB2)speed		Inj HP End						
Injection Press 1	40.00	PrePullbck before stro		Transfer						
Injection Press 2	90.00	Screw Start Delay		Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	
Injection Press 3		Screw Chg Position 1	1.90	Position 1 Gate/HB/Man						
Injection Press 4		Screw Chg Position 2		Position 2 Gate/HB/Man						_
Injection Press 5		Screw recovery % 1	30.00	Position 3 Gate/HB/Man						
Injection Velocity 1	5.00	Screw recovery % 2	35.00	Position 4 Gate/HB/Man						
Injection Velocity 2	600.00	Back Pressure 1	85.00	Position 5 Gate/HB/Man						_
Injection Velocity 3		Back Pressure 2	50.00	Position 6 Gate/HB/Man						Ī
Injection Velocity 4		PostPullback(PB1)speed	35.00	Start-Up Instructi	ions / Com	nents	,	'		
Injection Velocity 5		Post Pullback stroke in.	0.25							
Injection Change Pos 1	2.80	Screw positon after SB	3.31	Ī						
Injection Change Pos 2		Screw recovery time	14.22	Ī						
Injection Change Pos 3		Cooling time secs	21.00							
Injection Change Pos 4		Mold protect press	50.00	Ī						
Trans mode lvsh/lps	lvsh	Mold protect time	5.00							
Trans pos in.	0.20	Clamp tonnage	260	Ī						
lps PSI	2050	Injection pressure gauge	2050	Ī						
Inj PSI at transfer	2050	Holding 1 gauge psi	1000	Ī						
Injection time act. secs.	3.29	Holding 2 gauge psi	700	Ī						
Hold Press 1 %	40	Back pressure gauge psi	390							
Hold Press 2 %	35	Back pressure gauge psi	300]						
Hold Time 1	2.00	Final Cushion	0.05							
Hold Time 2										
Injection Hold Time	6.00									
				1						