

## **HUSKY**

## Run Sheet - CONFIDENTIAL

## **VALIDATING FORM**

6TGS135
11100
RSN CLR MKRN 2856-550042/
08/14/2018

Tool Number	6TGS#3	
Resin/Aditive Number		
Resin/Aditive Descrip		
	Std.	Cert.

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :			
Final Part(s) Weight (g	45.770	46.0	46.230

## ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data	'					
Nozzle Tip %		Mold Gate Temp °F		Fill Only Time	2.95	Machine Number: <b>H406</b>				
Nozzle Body %	25	Mold Fixed ½ °F	180	Fill Only Weight	43.0					
Adapter 1 (EX)	25	Mold Moving ½ °F	160	Steel Temp. "A" Side °F	182					
S/H Heat (EX)		Stripper or other °F		Steel Temp. "B" Side °F	150					
Barrel Head (EX)	580	Nozzle Tip Informa	ition	Melt Temp. °F	585					
Barrel Front (EX7)		Type GP, FT, NYL	GP	Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)	600	Length OAL (in.)	2 3/4	Open						
Barrel Center (EX5)	600	Orifice Size (in.)	3/16	Close						
Barrel Center (EX4)	600	Nozzle Body Information		PSI						
Barrel Center (EX3)	600	Length OAL (in.)	6.0	Delay						
Barrel Center (EX2)	580									
Barrel Rear (EX1)	570									
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	СЗ	C4		
Shot size in.	20.0	Pre-Pullback mm/s	9.00	Delay (Sec)						
Injection Velocity mm/s	3	Pre-Pullback Stroke m	9.00	Hold (Sec)						
Injection Velocity mm/s	15	Screw Start Delay	9.00	Exhaust (Sec)						
Injection Velocity mm/s	10	Screw Chg Position		Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	45	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM	45	Pessure 2 (PSI)						
Injection Change Pos 1	18.0	Back Pressure 1	180.0	Time (Sec)						
Injection Change Pos 2	8.0	Back Pressure 2	50.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s	20.00	Position 1 Gate/HB/Man						
Injection Change Pos 4		Post Pullback Stroke	4.00	Position 2 Gate/HB/Man						
Trans Pos. mm	6.00	Screw positon after SB	24.10	Position 3 Gate/HB/Man						
Injection Press Limit	2600	Screw recovery time	1.80	Position 4 Gate/HB/Man						
Inj PSI at transfer		Cooling time secs	11.8	Position 5 Gate/HB/Man						
Injection time act. secs.	2.95	Mold protect press	1000	Position 6 Gate/HB/Man						
Hold Press 1 PSI	500	Mold protect time		Start-Up Instructions / Comments						
Hold Press 2 PSI	35	Clamp tonnage	400							
Hold Press 1 secs	4.00	Injection pressure gauge	1584							
Hold Press 2 secs	3.00	Holding 1 gauge psi	500							
Final Cushion mm		Holding 2 gauge psi	350							
		Back pressure gauge psi								
		Back pressure gauge psi								