

HAITIAN

QUALIFY FORM

Product Name	SCP64CW135
Material Number	11100
Material Description	RSN CLR MKRN 2856-550042/
Date Created	06/06/2017

Tool Number	64OZSCOO	64OZSCOOP#2			
Resin/Aditive Number					
Resin/Aditive Descrip					
	Std.	Cert.			

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

	Standardization Info	Min.	Mid.	Max.
C	ertifield Cycle Time :			
Fi	nal Part(s) Weight (gm)	251.740	253.0	254.270

Final Part(s) Weight (gm)	251.740	253.0 254.270								
ALL DATA	BELOW IS F	REFERENCE ONLY AND SET	TTINGS CAI	N BE ADJUSTED IF REQUIR	RED IN ORDI	ER TO MEE	T PRODUC	T STANDA	RDS	
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data						
Nozzle Tip %	OFF	Mold Gate Temp °F		Fill Only Time	6.10	Machine Number: HT49				
Nozzle Body %	OFF	Mold Fixed ½ °F	180	Fill Only Weight	234.0					
Adapter 1 (HT1)	4	Mold Moving ½ °F	165	Steel Temp. "A" Side °F	167					
Barrel Front (HT2)	590	Stripper or other °F		Steel Temp. "B" Side °F	171					
Barrel Center (HT3)	600	Nozzle Tip Informa	ation	Melt Temp. °F	573					
Barrel Center (HT4)	600	Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (HT5)	590	Length OAL (in.)	0.00	Open	Tm/Pos	Tm/Pos	Tm/Pos	Tm/Pos		
Barrel Center (HT6)		Orifice Size (in.)	0.00	Time						
Barrel Center (HT7)		Nozzle Body Inform	nation	Pos						
Barrel Rear (HT8)		Length OAL (in.)	0.00	Close	Tm/Pos	Tm/Pos	Tm/Pos	Tm/Pos		
				Time						
				Pos						
Injection Profile	Injection Profile Set Recovery & Clamp Profile		Hold	On/Off	On/Off	On/Off	On/Off			
Shot size in.	3.20	Suckback Before Pos		Delay						
Injection Change Pos 1	3.04	Screw Start Delay		Active						
Injection Change Pos 2		Charge Position 1	1.50	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Charge Position 2		Position 1 Gate/HB/Man	640					
Injection Change Pos 4		Charge Pressure 1	755	Position 2 Gate/HB/Man	700					
Injection Press 1	400	Charge Pressure 2		Position 3 Gate/HB/Man						
Injection Press 2	1500	Charge Flow 1	45	Position 4 Gate/HB/Man						
Injection Press 3		Charge Flow 2	45	Position 5 Gate/HB/Man						
Injection Press 4		Back Pressure 1	350.0	Position 6 Gate/HB/Man						

Back Pressure 1 Injection Press 5 Back Pressure 2 350.0 Injection Flow 1 0.02 10 Suckback After Pos Injection Flow 2 75 Screw Positon After SB 3.63 Injection Flow 3 Screw charge Time Injection Flow 4 28.0 Cooling time secs Injection Flow 5 700 Mold protect press Inj Position threshold 1.00 80 Mold Protect Flow Inj Pressure threshold Mold protect time InjectionTime threshold Clamp High Press PSI 1555 Inj PSI at transfer 29 Clamp High Press Flow Injection time act. secs. 400 20.30 Injection pressure gauge Hold Press 1 PSI 650 650 Holding 1 gauge psi Hold Press 2 PSI 600 600 Holding 2 gauge psi Hold Flow 1 30 Back pressure gauge psi

30

7.00

7.00

1.00

Back pressure gauge psi

Start-Up Instructions / Comments

HAED 30 FILL - MUST PACK OUT PARTS

Source: Machine Run Database

Hold Flow 2

Hold Time 1

Hold Time 2

Final Cushion mm