

Version No.

VALIDATING FORM

HUSKY

Product Name	1014FF110
Material Number	11250
Material Description	RSN CP360H POLYPROPYLEI
Date Created	09/12/2017

1014FFSTACK			
Std.	Cert.		

Colorant Number	20328A
Colorant Descrip	CLR MC-80270PE BLACK
Color Percentage	1.00
MacGuire Setting	1.00

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	26.41	27.9	27.91
Final Part(s) Weight (g	495.510	498.0	500.490

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data	1	Machine Number: H401				
Nozzle Tip %		Mold Gate Temp °F		Fill Only Time	3.90					
Nozzle Body %		Mold Fixed ½ °F	65	Fill Only Weight	436.0					
Adapter 1 (EX)	420	Mold Moving ½ °F	65	Steel Temp. "A" Side °F	74					
S/H Heat (EX)	420	Stripper or other °F		Steel Temp. "B" Side °F	92					
Barrel Head (EX)	420	Nozzle Tip Informa	ation	Melt Temp. °F	421					
Barrel Front (EX7)	400	Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)	400	Length OAL (in.)	0.00	Open	135.0	135.0				
Barrel Center (EX5)	400	Orifice Size (in.)	0.00	Close						
Barrel Center (EX4)	395	Nozzle Body Inform	ation	PSI	120	120				
Barrel Center (EX3)	390	Length OAL (in.)	0.00	Delay						
Barrel Center (EX2)	385									
Barrel Rear (EX1)	380									
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	С3	C4		
Shot size in.	95.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	75	Pre-Pullback Stroke m	3.00	Hold (Sec)						
Injection Velocity mm/s	35	Screw Start Delay	2.00	Exhaust (Sec)						
Injection Velocity mm/s	6	Screw Chg Position	50.0	Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	110	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM	110	Pessure 2 (PSI)						
Injection Change Pos 1	85.0	Back Pressure 1	250.0	Time (Sec)						
Injection Change Pos 2	25.0	Back Pressure 2	250.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s		Position 1 Gate/HB/Man	550	550				
Injection Change Pos 4		Post Pullback Stroke		Position 2 Gate/HB/Man	550	550				
Trans Pos. mm	15.00	Screw positon after SB	103.50	Position 3 Gate/HB/Man		550				
Injection Press Limit	2600	Screw recovery time	8.75	Position 4 Gate/HB/Man		550				
Inj PSI at transfer	2450	Cooling time secs	14.0	Position 5 Gate/HB/Man		550				
Injection time act. secs.	3.94	Mold protect press	1800	Position 6 Gate/HB/Man						
Hold Press 1 PSI	1100	Mold protect time		Start-Up Instructi	ions / Com	ments				
Hold Press 2 PSI	1350	Clamp tonnage	400							
Hold Press 1 secs	3.00	Injection pressure gauge								
Hold Press 2 secs	3.00	Holding 1 gauge psi	1099							
Final Cushion mm	4.3	Holding 2 gauge psi	1320							
		Back pressure gauge psi	250							
		Back pressure gauge psi	250							
				T.						

Page 1 of 1 9:36:35AM

Validated by: