

HUSKY

Run Sheet - CONFIDENTIAL

VALIDATING FORM

Product Name	LT16152
Material Number	11114K
Material Description	RSN SAN 3301 KUMHO
Date Created	12/19/2017

Tool Number	16OZLAGTUMBLER					
Resin/Aditive Number						
Resin/Aditive Descrip						
	Std.	Cert.				

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.	
Certifield Cycle Time :	29.50	31.0	31.00	
Final Part(s) Weight (g	719.390	723.0	726.620	

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data						
Nozzle Tip %		Mold Gate Temp °F		Fill Only Time	3.00	Machine Number: H404				
Nozzle Body %	25	Mold Fixed ½ °F	150	Fill Only Weight	718.0					
Adapter 1 (EX)	25	Mold Moving ½ °F	100	Steel Temp. "A" Side °F	130					
S/H Heat (EX)		Stripper or other °F		Steel Temp. "B" Side °F	92					
Barrel Head (EX)		Nozzle Tip Informa	tion	Melt Temp. °F	410			_		
Barrel Front (EX7)		Type GP, FT, NYL	GP	Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)	405	Length OAL (in.)	2 3/4	Open						
Barrel Center (EX5)	415	Orifice Size (in.)	7/32	Close						
Barrel Center (EX4)	430	Nozzle Body Information		PSI						
Barrel Center (EX3)	440	Length OAL (in.)		Delay						
Barrel Center (EX2)	440									
Barrel Rear (EX1)	420									
Injection Profile	Set	Recovery & Clamp F	Profile	Gas Assist	C1	C2	С3	C4		
Shot size in.	180.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	35	Pre-Pullback Stroke m		Hold (Sec)						
Injection Velocity mm/s	40	Screw Start Delay		Exhaust (Sec)						
Injection Velocity mm/s	35	Screw Chg Position		Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	100	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM	130	Pessure 2 (PSI)						
Injection Change Pos 1	158.0	Back Pressure 1	240.0	Time (Sec)						
Injection Change Pos 2	40.0	Back Pressure 2	220.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s	20.00	Position 1 Gate/HB/Man	510	510	510			
Injection Change Pos 4		Post Pullback Stroke	8.00	Position 2 Gate/HB/Man	510	510				
Trans Pos. mm	33.00	Screw positon after SB	188.00	Position 3 Gate/HB/Man	510	510				
Injection Press Limit		Screw recovery time	9.32	Position 4 Gate/HB/Man	510	510				
Inj PSI at transfer		Cooling time secs	16.0	Position 5 Gate/HB/Man	510	510				
Injection time act. secs.	3.00	Mold protect press	50	Position 6 Gate/HB/Man	510	510				
Hold Press 1 PSI	450	Mold protect time		Start-Up Instructions / Comments						
Hold Press 2 PSI	375	Clamp tonnage	400							
Hold Press 1 secs	5.00	Injection pressure gauge	1302							
Hold Press 2 secs	3.00	Holding 1 gauge psi	450							
Final Cushion mm		Holding 2 gauge psi	375							
		Back pressure gauge psi								

Back pressure gauge psi