HAITIAN

Run Sheet - CONFIDENTIAL

VALIDATING FORM

Product Name	10146DCPC190
Material Number	11160
Material Description	RSN R12C-01 CLARFD PP
Date Created	11/02/2018

Tool Number	10146DC	10146DC		
Resin/Aditive Number				
Resin/Aditive Descrip				
	Std.	Cert.		

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	49.20	50.7	50.70
Final Part(s) Weight (gm)	271.640	273.0	274.370

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

ALL DATA BELOW IS REFERENCE UNLY AND SETTINGS CAN BE ADJUSTED IF REQUI				
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data
Nozzle Tip %	6	Mold Gate Temp °F	65	Fill Only Time
Nozzle Body %	5	Mold Fixed ½ °F	65	Fill Only Weight
Adapter 1 (HT1)	380	Mold Moving ½ °F	185	Steel Temp. "A" Side °F
Barrel Front (HT2)	400	Stripper or other °F		Steel Temp. "B" Side °F
Barrel Center (HT3)	400	Nozzle Tip Informa	ation	Melt Temp. °F
Barrel Center (HT4)	400	Type GP, FT, NYL	GP	Valve Gate
Barrel Center (HT5)	390	Length OAL (in.)	2 3/4	Open
Barrel Center (HT6)		Orifice Size (in.)	1/4	Time
Barrel Center (HT7)		Nozzle Body Inform	Nozzle Body Information	
Barrel Rear (HT8)		Length OAL (in.)	6.00	Close
	•			Time
				Pos
Injection Profile	Set	Recovery & Clamp I	Profile	Hold
Shot size in.	4.00	Suckback Before Pos		Delay
Injection Change Pos 1	3.80	Screw Start Delay		Active
Injection Change Pos 2	1.60	Charge Position 1	1.60	Hot Tip Controller
Injection Change Pos 3		Charge Position 2		Position 1 Gate/HB/Man
Injection Change Pos 4		Charge Pressure 1	850	Position 2 Gate/HB/Man
Injection Press 1	700	Charge Pressure 2		Position 3 Gate/HB/Man
Injection Press 2	700	Charge Flow 1	60	Position 4 Gate/HB/Man
Injection Press 3	500	Charge Flow 2	55	Position 5 Gate/HB/Man
Injection Press 4		Back Pressure 1	160.0	Position 6 Gate/HB/Man
Injection Press 5		Back Pressure 2	160.0	Start-Up Instruc
Injection Flow 1	20	Suckback After Pos	0.10	VERIFY LID FIT BEFORI
Injection Flow 2	20	Screw Positon After SB	4.17	72Kii 1 213 111 321 31Ki
Injection Flow 3	30	Screw charge Time	6.8	
Injection Flow 4		Cooling time secs	25.0	
Injection Flow 5		Mold protect press	29	
Inj Position threshold	0.75	Mold Protect Flow	40	
Inj Pressure threshold		Mold protect time	5.00	
InjectionTime threshold		Clamp High Press PSI	2000	
Inj PSI at transfer	800	Clamp High Press Flow	18	
Injection time act. secs.	5.70	Injection pressure gauge	800	
Hold Press 1 PSI	450	Holding 1 gauge psi	600	
Hold Press 2 PSI	400	Holding 2 gauge psi	550	
Hold Flow 1	35	Back pressure gauge psi		
Hold Flow 2	35	Back pressure gauge psi		•
Hold Time 1	5.00			
Hold Time 2	5.00			
Final Cushion mm				
		•		•

Machine Number: **HT43**

VG3

Tm/Pos

Tm/Pos

On/Off

Box 3

VG4

Tm/Pos

Tm/Pos

On/Off

Box 4

Box 5

Box 6

5.70

271.0

79 188

391

VG2

Tm/Pos

Tm/Pos

On/Off

Box 2

VG1

Tm/Pos

Tm/Pos

On/Off

Box 1

420

420

Start-Up Instructions / Comments

IFY LID FIT BEFORE RUN.