




Matrices de transformación

$${}^0T_1: {}^0Z_1, R_z(180^\circ + \theta_1)$$

$${}^1T_2: {}^1X_2, R_x(-90^\circ), {}^1Z_2, R_z(\theta_2)$$

$${}^2T_3: {}^2X_3, R_z(\theta_3)$$

$${}^3T_4: {}^3X_4, {}^3Z_4, R_z(\theta_4)$$

$${}^4T_5: {}^4X_5, R_z(\theta_5)$$

$${}^5T_P: {}^5X_P$$