Kernel Changelog:

- 1. TXL (T962) bring up: p320 & p321
- 2. cpuldle and broadcast timer
- 3. optimize mm:CMA
- 4. fix: vcck_b affected by bt.
- 5. fs: add ntfs format support in defconfig
- 6. usb power consumption reduction and fix bug
- 7. add new functions and fix bugs in: amports, h264/265, Idim, amvecm
- 8. fix driver bugs in: osd, audio,eth phy ,hdmi tx/rx/cec, vpp, amlvideo2,vdin, jpegdec

Uboot Changelog:

- 1. TXL add thermal support.
- 2. TXL gpio/ddr config update.
- 3. Add TXL(T962) P320 reference board support.
- 4. Add TXL(T962) P321 reference board support.
- 5. GXM(S912) suspend/shutdown bug fix.
- 6. GXtvbaby(T968/T966) pll init flow optimize.
- 7. uboot DHCP cmd fix.
- 8. NAND driver optimize & bug fix.