
8 channel RS485 control card

assembly manual


step 1: IC sockets

- 5 x 8 pin, 1 x 28 pin
- watch orientation



step 2: resistors

- 8 + 3 x 330R (orange, orange brown)
- 8 x 10R (brown, black, black)




step 3: xtal and car

 2 x 22pF capacitors, don't confuse with 100nF

• 16MHz xtal, solder briefly!


bend wires to fit2.54 mm space



step 4: diodes


- 8 x 1N4007
- watch orientation
- bend wires at 5mm from body

stripe on this side




step 5, 100n cap

- 9 x 100 nF capacitor
- 6 x next to IC socket, 3 x in power supply section



step 6: connector


- 2 x 8 pin or 1 x 16 pin
- need to bend legs a bit outwards to fit, since the PCB is intended for 8 x 2 pins






step 7: dip switch


- check orientation, the unit will work but reversal is highly confusing:)
- (so, the text should be legible from the side)



step 8a


 collect 8 IRFZ44 FET and 1 LM7812 regula (both TO220 but the has different thicknes






step 8b

 mount 8 FETs, legs can get in all the way (mount flush at PCB side)



step 9: LM7812


 mount the linear regulator (LM7812)




step 10: LEDs

- watch orientation! long wire (+) should go in square pad!
- 8 green LEDs at the FET side have the (+) left as shown ->
- three leds, (yellow, green, red) at the bottom have the (+) right. Please keep this order!









step 11: RJ45

- Two RJ 45 sockets
- plastic strip on side of ONE of the sockets need to be taken off (knife, pliers) in order to fit




step 12 regulator

- Traco Power TSR 1-2450 regulator
- sloppy pin fit: mount as much on the PCB as possible




step 13 elcos

- mount three elco's
- watch polarisation: stripe on side is (-)
- (+) side should go in square pad
- check sizes



step 14: fuse

mount the fuse




step 15: pin headers

2 x (1x6 pin)


• 1 x (1x3 pin)

• 1 x (2x3 pin) ISP (not in this picture)



step 16 IC's

- (check!) 4 x TC4423 (in a row)
- 1 x MAX485 (or sipex or similar) next to the RJ45 sockets



- 1 x ATmega88
- carefully bend the legs a bit (on the side on table)
- check orientation!

