





HARVEST CECTION DRIVE SETTING

KATS DRIVE

P0-02 1 P0.03 0 P0.09 0 P0.10 50 P0.17 1 P0.18 1 P1.00 0 P1.01 1.5 P1.02 380 P1.03 3 P1.04 50 P1.05 1460 P9.00 1 P9.01 1 PD.00 5 PD.01 1 PD.02 2

GARRY DRIVE

P0-02	1
P0.03	0
P0.09	0
P0.10	50
P0.17	3
P0.18	1
P1.00	0
P1.01	1.5
P1.02	380
P1.03	3
P1.04	50
P1.05	1460
P9.00	1
P9.01	1
PD.00	5
PD.01	1
PD.02	3

WAGON DRIVE

04