DATE: -13-FEB-2026

Preventive Maintenance (PM) & Safety Inspection Report

Report Date: March 4, 2026
Customer: Ecom Logistics

Equipment Inspection Details

Unit	Make	Model	Serial Number	Status / Findings
1	Raymond	752R45TT	752-20-AD78747	PM completed and safety inspection passed. Inspection sticker attached.
2	Raymond	752-R4TT	752-20-AD78713	PM completed – **Safety Failed.** Hose pulley is broken. **Action Required:** Replace damaged hose pulley and inspect the hose assembly.
3	Raymond	540-OPD30TT	540-12-B15230	PM completed and safety inspection passed. Inspection sticker attached.
4	Raymond	540-OPC30TT	540-12-B15231	PM completed and safety inspection passed. Inspection sticker attached.
5	Raymond	540-OPC30TT	540-12-B15235	PM completed and safety inspection passed. Inspection sticker attached.
6	Toyota	8FBE20U	14455	PM completed and safety inspection passed. Inspection sticker attached.
7	Raymond	520-OPC30TT	520-15-04181	PM completed and safety inspection passed. Inspection sticker attached.
8	Raymond	EASI DR30TT	EZ-D-04-30478	**Safety Failed – Operator protection guard missing.** PM completed.
9	Walkie	8400	840-06-70324	PM completed and safety inspection passed. Inspection sticker attached.
10	Raymond	840-FRE60L	840-06-66956	Battery cable replacement required. Battery service required. **Action Required:** Replace cable and perform battery service and PM.
11	Sumachay Lifts	SELR20	9923120C4401	PM completed and safety inspection completed. Inspection sticker attached.
12	Factory Cat	XRV240C	151441	**Safety Failed.** Hose cap broken and noisy operation while driving. **Action Required:** Further mechanical diagnosis and inspection required.

OK LIFT LTD
416-407-0762
info@oklift.ca
www.oklift.ca