

HPE ProLiant DL Gen10 Server - Installing Innovation Engine and Server Platform Services from ILO Webpage

Table of contents

- Objective
- Environment
- Steps

Objective

Before we do any of the mentioned update IE or SPS, power off the server.

Environment

- HPE ProLiant DL Gen10 Server
- Running any Operating system
- ILO5 is configured

Steps

Steps to install Innovation Engine update-

- Power off the server before the update
- Download the Innovation engine firmware
- Extract the .exe file (you will get exe again, so extract any of the exe again) to get .bin file
- Go to ILO page and browse to 'Firmware and OS Software' tab and under it "Update firmware"
- Browse the extracted bin file and upload it
- Once update is completed, restart the server

Steps to install Server Platform Services update-

- Power off the server before the update
- Download the SPS firmware
- Extract the .exe file (you will get exe again, so extract the exe again) to get signed .bin file
- Go to ILO page and browse to 'Firmware and OS Software' tab and under it "Update firmware"
- Browse the extracted bin file and upload it
- Once update is completed, restart the server