

HPE Proliant DL380 Gen10 TPM Visibility option greyed out

Table of contents

- Issue
- Environment
- Cause
- Resolution

Issue

Customer has upgraded the SPP 2022.3.0 from 2021.10.0 in 10 servers and in all the servers TPM Visiblity option greyed out

Environment

HPE-Proliant-DL380-Gen10-TPM-V is ibility-option-greyed-out

Operating System: All affected

Cause

Customer has upgraded the SPP 2022.3.0 from 2021.10.0 in 10 servers and in all the servers TPM Visiblity option greyed out

Resolution

Go to RBSU by pressing F9

Then go to Server security and disable the Platform Certificate support