Region	Supervisor	Concept	¬¸ĺ¥¹	³¸°žĺœ	¬ ³/4 " ³/4	a®iDz	¶¹°	,ĺΫÇΫ	¦Ç¶	Off Hours Runtime	% ¬³¼‡° Ÿ¾°Í	34 a [2 34 : Ç ¤ 34 a — a ° [- 34 - 1/2] 34 a [2 34 ; 13 34 a a o [- 34 - 1/2	— ½ Dz m³¼ a a ° -3¼ - 1⁄4	— i ¼ i Ç ² m ¾ a a ∘ í - ¾ - ¼	Excess Runtime (min)	Excess Runtime Cost
QUAD States	Masi Carter	Wings	#0086	RTU 2 (Dining)	York	lgh092h4bh1y	Collierville	11	Cocos [Keeling] Islands		62%					32	\$2
QUAD States	Masi Carter	Wings	#0257	RTU 2 (Dining)	Lennox	tga120s2bm1y	Horn Lake	MS	USA		73%					50	\$1
Eastern Michigan	M Houston-Barocko	Wings	#0313	RTU 1 (Kitchen)		48tjd014-521	Bay City	МІ	USA		86%	21.7 °C		-18.9 °C		49	\$0
Minnasota/North	T Olson	Fine Dining	#0611	RTU 4 (Kitchen)			Roseville	MN	USA		54%					27	\$1
Indiana Elite	L Samples	Fast Food	#5534	RTU 1 (Kitchen)	Carrier	48hjd008-542hs	Indianapolis	IN	USA		49%					27	
Pittsburgh	J Fennel	Fast Food	#7683	RTU 1 (Kitchen)		lgc120s2bs2y	Hiram	GA	USA		56%	16.1 °C	18.3 °C	-23.9 °C	-22.8 °C	38	\$0
Eastern Michigan	J Peters	Fast Food	#7695	RTU 3 (Front Line)	Lennox	lgh060h4em	Portland	TN	USA		99%					70	
Eastern Michigan	J Peters	Fast Food	#7695	RTU 1 (Service)		KGB060S4BHY	Portland	TN	USA		100%					90	
Florida	H Bouhamdan	Open 24	Lexington	RTU 2 (Dining)	Carrier	48hje008-541hq	Lexington	Kentucky	United States		46%					25	\$4