

2. LIMITATIONS

2.1 OCCUPANTS

When the Centerline Bench Seat is installed the helicopter is approved as a six-place rotorcraft.

EFFECTIVITY *For IAC-AR registered helicopters only*

Only those persons familiar with emergency evacuation procedures shall be seated on the Centerline Bench Seat.

EFFECTIVITY *ALL*

3. EMERGENCY AND MALFUNCTION PROCEDURES

No change in the basic Flight Manual data.

4. NORMAL PROCEDURES

4.1 PREFLIGHT CHECK

Bench — Secured, correctly installed

NOTE Bench must be so installed that the shoulder harness belt lies over the RH shoulder of passengers seated on the RH side and the LH shoulder of passengers seated on the LH side.

5. PERFORMANCE DATA

No change in the basic Flight Manual data.