

F M S 10 - 19**SUPPLEMENT FOR****GENERATOR TRIP/RESET CONTROLS****1. GENERAL**

This supplement shall be attached to the BO 105 Flight Manual (Section 10) when the GENERATOR TRIP/RESET CONTROLS have been installed.

System/Equipment Designation	Part No.	Effectivity
Retrofit Voltage Regulator	105-90039	0161-9999

The information contained herein supplements the information of the basic Flight Manual; for limitations, procedures, and performance data not contained in this supplement, refer to the basic Flight Manual.

NOTE For approving authorities and original issue date of this supplement, refer to the Log of Supplements.