```vhdl
        -- manage scantimeup
        scan <= '0', '1' after 1405 ns, '0' after 1415 ns;

    end test1;

    library work;
    configuration config1 of work.testRobot is
        for test1
            for A:Robot use entity work.Robot(automate_robot);
            end for;
        end for;
    end config1;
```